AD/CF6/4 High Pressure Turbine Rotor Spacer/Impeller Inspection Requirements 2/88

CANCELLED.

Background: FAA AD 87-23-06 General Electric: Amendment 39-5746 and GE Service Bulletin 72-906 introduce more stringent inspection and component retirement requirements than those specified in the Requirement Documents of AD/CF6/4. The revised inspection requirements have been reissued as AD/CF6/9.