AD/CF6/21 Eddy Current Inspection of High Pressure Turbine Thermal Shields 11/91

Applicability: CF6-45/-50 series engines.

Requirement: Action in accordance with the Technical Requirements of FAA AD 91-15-16, Amendment 39-7080.

Note: General Electric Service Bulletin 72-879 Revision 6 refers.

Compliance: As specified in the Requirement Document with an effective date of 28 November 1991.

Background: Four HPT stage one discs have been found cracked during inspection. The condition, if not corrected could result in uncontained engine failure.