AD/CF6/17 Stage 1 Fan Rotor Disc 3/91

Applicability: CF6 - 6, -45, -50, -80A.

Requirement: Inspect the stage 1 fan disc dovetail post for cracks in accordance with the technical requirements of the FAA AD 91-01-04 Amdt 39-6847.

Note: The GE SB 72-999, 965 and 575 covering the -50/-45, -6 and -80A series respectively refer.

Compliance: As specified in the Requirement Document.

Background: Five stage 1 fan discs have been discovered with cracks in the dovetail post area. The defect has the potential for multiple blade release, engine power loss and uncontained engine failure.