AD/CF6/26 Stage 11 to 13 Compressor Spool Inspection 12/93

Applicability: CF6-45/-50 series.

Requirement: Action in accordance with the technical requirements of FAA AD 93-13-10.

Note: GE Service Bulletin No 72-1006 Revision 1 dated 14 November 1991 refers.

Compliance: As specified in the FAA AD with effectivity commencing 11 November 1993.

Background: There have been reports of fatigue cracking in the 12th stage compressor disc. Consequently, there is need for a one time inspection for cracking and measurement of the stage 12 compressor disc web-to-rim transition area of the stage 11-13 compressor spool. Depending on the results, the items are then to be replaced, reidentified and relifed.