# Airworthiness Directive

**AD No.:** **2020-0007**

**Issued:** **15 January 2020**

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

**Design Approval Holder's Name:**
CFM INTERNATIONAL S.A.

**Type/Model designation(s):**
CFM56-5B, CFM56-5C and CFM56-7B engines

Effective Date: 29 January 2020

TCDS Number(s): EASA.E.003 and EASA.E.004

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2019-0150 dated 28 June 2019.

## ATA 72 – Engine – Rotating Air High Pressure Turbine Front Seal – Replacement

---

**Manufacturer(s):**
SAFRAN Aircraft Engines, formerly SNECMA (France); General Electric Aircraft Engines (United States)

**Applicability:**
CFM56-5B1, CFM56-5B2, CFM56-5B4, CFM56-5B5, CFM56-5B6, CFM56-5B7, CFM56-5B1/P, CFM56-5B2/P, CFM56-5B3/P, CFM56-5B4/P, CFM56-5B5/P, CFM56-5B6/P, CFM56-5B7/P, CFM56-5B8/P, CFM56-5B9/P, CFM56-5B3/P1, CFM56-5B4/P1, CFM56-5B1/2P, CFM56-5B2/2P, CFM56-5B3/2P, CFM56-5B4/2P, CFM56-5B6/2P, CFM56-5B9/2P, CFM56-5B3/2P1 and CFM56-5B4/2P1 engines, all serial numbers (s/n);

CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/G4, CFM56-5C2/P, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P and CFM56-5C4/1P engines, all s/n; and

CFM56-7B20, CFM56-7B22, CFM56-7B24, CFM56-7B26, CFM56-7B27, CFM56-7B22/B1, CFM56-7B24/B1, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B20/2, CFM56-7B22/2, CFM56-7B24/2, CFM56-7B26/2, CFM56-7B27/2 and CFM56-7B27A engines, all s/n.

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

These engines are known to be installed on, but not limited to, Airbus A318, A319, A320, A321 and A340 aeroplanes, and Boeing 737-600, 737-700, 737-800 and 737-900 aeroplanes.

## Definitions:

For the purpose of this AD, the following definitions apply:

**The applicable S/B**: CFM International CFM56-5B Service Bulletin (S/B) 72-1074, CFM56-5C S/B 72-0794 and CFM56-7B S/B 72-1042, as applicable.

**Affected part**: Rotating air high pressure turbine (HPT) front seals, having part number (P/N) 1795M36P01 or P/N 1795M36P02, and having a s/n as identified in Appendix 1 (P/N 1795M36P01) or Appendix 2 (P/N 1795M36P02) of this AD, except those for which one of the conditions (a) or (b) below applies:

(a) The HPT front seal is new (not previously installed on an engine), or

(b) The HPT front seal has never been removed from its original HPT disk and re-installed onto a different HPT disk.

**Serviceable part**: Any rotating air HPT front seal that is not an affected part.

**Groups**:

Group 1 engines are those that have an affected part installed.

- Subgroup 1A are: CFM56-5B and CFM56-7B engines, having an affected part that, following re-installation, has never been operated on a CFM56-5C engine.
- Subgroup 1B are CFM56-5B and CFM56-7B engines, having an affected part that, following re-installation, has been operated at any time on a CFM56-5C engine.
- Subgroup 1C are CFM56-5C engines.

Group 2 engines are those that do not have an affected part installed.

**Re-installation**: For an affected part, first in-service re-installation on an HPT disc other than the HPT disc on which that affected part was originally installed in production.

## Reason:

Occurrences have been reported of finding cracked rotating air HPT front seals during in-shop inspections. Subsequent investigation determined that certain rotating air HPT front seals, if removed from an HPT disc and re-installed on a different HPT disc, may be susceptible to similar cracks.

This condition, if not detected and corrected, could lead to uncontained engine failure, possibly resulting in damage to the aeroplane, with consequent reduced control of the aeroplane.

To address this potential unsafe condition, CFM International issued the applicable S/B, providing instructions to replace the affected parts. Consequently, EASA issued AD 2019-0146 to require removal from service of the affected parts and to prohibit re-installation thereof.

After that AD was issued, prompted by operator comments, EASA issued AD 2019-0150, retaining the requirements of EASA AD 2019-0146, which was superseded, including clarifications, reference



TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

to the applicable Engine Shop Manual for the existing life limits (not to be exceeded) and providing a full list of the affected serial numbers (Appendices 1 and 2).

Prompted by further operator comments, this AD retains the requirements of EASA AD 2019-0150, which is superseded, and introduces reduced life limits for affected parts which have been previously installed on different engine models. This AD also excludes from the definition of "affected part" certain parts, for which an installation requirement is added.

## Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

**Part Replacement**:

(1) For Group 1 engines: Within the compliance time as defined in Table 1 of this AD, as applicable, but without exceeding the applicable life limit as specified in Chapter 05 of the applicable Engine Shop Manual, replace the affected part with a serviceable part, as defined in this AD, in accordance with the instructions of the applicable S/B.

Table 1 – Affected Parts Replacement

| **Engine(s)** (all models) | **Compliance time** (**A, B**, **C** or **D**, whichever occurs later, as applicable) |
|---|---|
| Subgroup 1A | **A**: Within 6 500 engine cycles (EC) since re-installation |
| | **B**: Within 500 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 7 000 EC since re-installation |
| | **C:** Within 50 EC after 05 July 2019 [the effective date of EASA AD 2019-0150] |
| Subgroup 1B | **A**: Within 4 000 EC since re-installation |
| | **B**: Within 250 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 4 250 EC since re-installation |
| | **C:** Within 1 500 EC since last seal piece-part fluorescent penetrant inspection |
| | **D:** Within 25 EC after the effective date of this AD, but not exceeding the compliance time applicable for Subgroup 1A engines |
| Subgroup 1C | **A**: Within 4 000 EC since re-installation |
| | **B**: Within 250 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 4 250 EC since re-installation |
| | **C:** Within 1 500 EC since last seal piece-part fluorescent penetrant inspection |
| | **D:** Within 25 EC after 05 July 2019 [the effective date of EASA AD 2019-0150] |

**Limitations:**

(2) From the effective date of this AD, do not operate an aeroplane having two Subgroup 1A engines installed, or two Subgroup 1B engines, or a combination thereof, equipped with an

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

affected part having accumulated 6 500 EC (Subgroup 1A) or more, or 4 000 EC (Subgroup 1B) or more since re-installation.

(3) From the effective date of this AD, do not operate an aeroplane having two or more Subgroup 1C engines installed, equipped with an affected part having accumulated 4 000 EC or more since re-installation.

**Part(s) Installation:**

(4) For Group 1 and Group 2 engines: From 05 July 2019 [the effective date of EASA AD 2019-0150], do not install (see Note 1 of this AD) an affected part on any engine.

Note 1: The following actions, accomplished during a single maintenance visit, are not considered as 'installation' as specified in paragraph (4) of this AD: Removing an affected part from its HPT disc and re-installing that affected part on the same disc on the same engine; removing an HPT disc equipped with an affected part and re-installing that disc, with that affected part, on the same engine.

(5) For Group 1 and Group 2 engines: From the effective date of this AD, do not re-install a serviceable part, having P/N 1795M36P01 or P/N 1795M36P02, and having a s/n as identified in Appendix 1 (P/N 1795M36P01) or Appendix 2 (P/N 1795M36P02) of this AD, on any HPT disk different from the HPT disk on which that serviceable part was previously installed.

**Ref. Publications:**

CFM International S.A. CFM56-5B S/B 72-1074 original issue dated 27 July 2018, or Revision 01 dated 05 December 2018, or Revision 02 dated 06 November 2019.

CFM International S.A. CFM56-5C S/B 72-0794 original issue dated 14 September 2018, or Revision 01 dated 02 January 2019, or Revision 02 dated 06 November 2019.

CFM International S.A. CFM56-7B S/B 72-1042 original issue dated 27 July 2018, or Revision 01 dated 02 January 2019, or Revision 02 dated 06 November 2019.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD

2. This AD was posted on 12 December 2019 as PAD 19-212 for consultation until 26 December 2019. No comments were received during the consultation period.

3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.

4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on


TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

a product, part or appliance not affected by this AD, can be reported to the EU aviation safety reporting system.

5. For any question concerning the technical content of the requirements in this AD, please contact: CFM International S.A., Customer Support Centre, Telephone: +33 1 64 14 88 66, Fax: +33 1 64 79 85 55, E-mail: cfm.csc@safrangroup.com;
or

CFM Inc. Aviation Operations Centre, Telephone: +1 513-552-3272, or +1 877-432-3272, Fax: +1 877-432-3329, E-mail: geae.aoc@ge.com, or aviation.fleetsupport@ge.com.



TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 1 – P/N 1795M36P01 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNDN949 | GWNDS079 | GWNKC901 | GWNKE207 | GWNKF192 | GWNKG219 |
| GWNDP018 | GWNDS080 | GWNKC902 | GWNKE320 | GWNKF193 | GWNKG220 |
| GWNDP019 | GWNDS081 | GWNKC903 | GWNKE321 | GWNKF194 | GWNKG397 |
| GWNDP020 | GWNDS380 | GWNKD506 | GWNKE322 | GWNKF288 | GWNKG398 |
| GWNDP021 | GWNDS381 | GWNKD507 | GWNKE598 | GWNKF289 | GWNKG399 |
| GWNDP901 | GWNDS382 | GWNKD508 | GWNKE599 | GWNKF314 | GWNKG400 |
| GWNDP902 | GWNDS383 | GWNKD723 | GWNKE600 | GWNKF315 | GWNKG686 |
| GWNDP903 | GWNDS384 | GWNKD724 | GWNKE601 | GWNKF316 | GWNKG687 |
| GWNDP904 | GWNDS385 | GWNKD725 | GWNKE602 | GWNKF317 | GWNKG688 |
| GWNDP905 | GWNDS387 | GWNKD726 | GWNKE603 | GWNKF676 | GWNKG689 |
| GWNDP906 | GWNDS388 | GWNKD727 | GWNKE604 | GWNKF677 | GWNKG814 |
| GWNDP907 | GWNDS592 | GWNKD732 | GWNKE840 | GWNKF678 | GWNKG816 |
| GWNDR152 | GWNDS653 | GWNKD796 | GWNKE841 | GWNKF679 | GWNKG817 |
| GWNDR402 | GWNDS654 | GWNKD797 | GWNKE842 | GWNKF680 | GWNKH129 |
| GWNDR403 | GWNDS874 | GWNKD798 | GWNKE893 | GWNKF681 | GWNKH130 |
| GWNDR404 | GWNDS875 | GWNKD824 | GWNKE894 | GWNKF682 | GWNKH131 |
| GWNDR405 | GWNDS876 | GWNKD825 | GWNKE895 | GWNKF683 | GWNKH132 |
| GWNDR406 | GWNDS877 | GWNKD826 | GWNKE897 | GWNKF684 | GWNKH133 |
| GWNDR529 | GWNDS935 | GWNKD827 | GWNKF015 | GWNKG073 | GWNKH395 |
| GWNDR530 | GWNDS937 | GWNKD828 | GWNKF016 | GWNKG074 | GWNKH397 |
| GWNDR531 | GWNDS938 | GWNKE045 | GWNKF017 | GWNKG075 | GWNKH525 |
| GWNDR532 | GWNDT152 | GWNKE046 | GWNKF107 | GWNKG076 | GWNKH526 |
| GWNDR955 | GWNKC168 | GWNKE047 | GWNKF108 | GWNKG077 | GWNKH527 |
| GWNDR956 | GWNKC170 | GWNKE048 | GWNKF109 | GWNKG078 | GWNKH528 |
| GWNDR957 | GWNKC173 | GWNKE049 | GWNKF110 | GWNKG080 | GWNKH529 |
| GWNDR958 | GWNKC174 | GWNKE050 | GWNKF111 | GWNKG081 | GWNKH530 |
| GWNDR960 | GWNKC175 | GWNKE205 | GWNKF112 | GWNKG217 | GWNKH531 |
| GWNDS078 | GWNKC900 | GWNKE206 | GWNKF113 | GWNKG218 | |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN000CE | GWN0028J | GWN0037L | GWN006MC | GWN006P2 | GWN009P7 |
| GWN000CF | GWN0028K | GWN0037M | GWN006MD | GWN006P3 | GWN009P8 |
| GWN000CG | GWN0028L | GWN0041F | GWN006ME | GWN006P4 | GWN009P9 |
| GWN000CH | GWN0028M | GWN0041G | GWN006MF | GWN006P5 | GWN009PA |
| GWN000CJ | GWN0028N | GWN0041H | GWN006MG | GWN0073G | GWN009PC |
| GWN000CK | GWN0028R | GWN0041J | GWN006MH | GWN00757 | GWN009PD |
| GWN000CL | GWN0028T | GWN0041K | GWN006MJ | GWN008EC | GWN009PE |
| GWN000CM | GWN0028V | GWN0041L | GWN006MK | GWN008ED | GWN009PF |
| GWN000CN | GWN0028W | GWN0041M | GWN006ML | GWN008EE | GWN009PG |
| GWN000CP | GWN0028Y | GWN0041N | GWN006MM | GWN008EF | GWN009PH |
| GWN000CR | GWN00290 | GWN0041P | GWN006MN | GWN008EG | GWN009PJ |
| GWN000CT | GWN002WD | GWN0041R | GWN006MP | GWN008EH | GWN009PK |
| GWN000CV | GWN002WE | GWN0041T | GWN006MR | GWN008EJ | GWN009PL |
| GWN000CW | GWN002WG | GWN0041V | GWN006MT | GWN008EK | GWN009PM |
| GWN000CY | GWN002WH | GWN0041W | GWN006MV | GWN008EL | GWN009PN |
| GWN000D0 | GWN002WJ | GWN0041Y | GWN006MW | GWN008EM | GWN00AV5 |
| GWN000D2 | GWN002WK | GWN00420 | GWN006MY | GWN008EN | GWN00AV6 |
| GWN000D3 | GWN002WL | GWN00421 | GWN006N0 | GWN008EP | GWN00AV7 |
| GWN000D4 | GWN002WM | GWN00422 | GWN006N1 | GWN008ER | GWN00AV8 |
| GWN001G3 | GWN002WN | GWN00423 | GWN006N2 | GWN008ET | GWN00AV9 |
| GWN001G4 | GWN002WP | GWN00424 | GWN006N3 | GWN008EV | GWN00AVA |
| GWN001G5 | GWN002WR | GWN00425 | GWN006N4 | GWN008EW | GWN00AVC |
| GWN001G6 | GWN002WT | GWN004WM | GWN006N6 | GWN008EY | GWN00AVD |
| GWN001G7 | GWN002WV | GWN004WN | GWN006N7 | GWN008F0 | GWN00AVE |
| GWN001G8 | GWN002WW | GWN004WP | GWN006N8 | GWN00920 | GWN00AVF |
| GWN001G9 | GWN002WY | GWN004WR | GWN006N9 | GWN00921 | GWN00AVG |
| GWN001GA | GWN002Y0 | GWN004WT | GWN006NA | GWN00922 | GWN00CTK |
| GWN001GC | GWN002Y1 | GWN0052H | GWN006NC | GWN00923 | GWN00CTL |
| GWN001GD | GWN002Y2 | GWN0052J | GWN006ND | GWN00924 | GWN00CTM |
| GWN001GE | GWN0036Y | GWN0052K | GWN006NE | GWN00925 | GWN00CTN |
| GWN001GF | GWN00371 | GWN0052L | GWN006NF | GWN00926 | GWN00CTP |
| GWN001GG | GWN00372 | GWN0052M | GWN006NG | GWN00927 | GWN00CTR |
| GWN001GH | GWN00373 | GWN0052N | GWN006NH | GWN00928 | GWN00CTT |
| GWN001GJ | GWN00374 | GWN0052P | GWN006NJ | GWN00929 | GWN00CTV |
| GWN001GK | GWN00376 | GWN0052R | GWN006NK | GWN0092A | GWN00CTW |
| GWN001GL | GWN00377 | GWN0052T | GWN006NL | GWN0092C | GWN00CTY |
| GWN001GM | GWN00378 | GWN0052V | GWN006NM | GWN0092D | GWN00CV0 |
| GWN001GN | GWN00379 | GWN0052Y | GWN006NN | GWN0092E | GWN00CV1 |
| GWN001GP | GWN0037A | GWN00530 | GWN006NP | GWN0092F | GWN00CV2 |
| GWN00289 | GWN0037C | GWN00531 | GWN006NR | GWN0092G | GWN00CV3 |
| GWN0028A | GWN0037D | GWN00532 | GWN006NT | GWN0092H | GWN00CV4 |
| GWN0028C | GWN0037E | GWN00533 | GWN006NV | GWN0092J | GWN00CV5 |
| GWN0028D | GWN0037F | GWN00534 | GWN006NW | GWN009NW | GWN00CV6 |
| GWN0028E | GWN0037G | GWN00535 | GWN006NY | GWN009P4 | GWN00DGM |
| GWN0028G | GWN0037H | GWN006M9 | GWN006P0 | GWN009P5 | GWN00DGN |
| GWN0028H | GWN0037K | GWN006MA | GWN006P1 | GWN009P6 | GWN00DGP |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN00DGR | GWN00FDG | GWN00HDD | GWN00LDG | GWN00MH3 | GWN00P4V |
| GWN00DGT | GWN00FDH | GWN00HDE | GWN00LDH | GWN00MH4 | GWN00P4W |
| GWN00E20 | GWN00G1R | GWN00HDF | GWN00LDJ | GWN00MH5 | GWN00P4Y |
| GWN00E22 | GWN00G1T | GWN00HDG | GWN00LDK | GWN00MH7 | GWN00P50 |
| GWN00E23 | GWN00G1V | GWN00HDH | GWN00LDL | GWN00MH8 | GWN00P51 |
| GWN00E25 | GWN00G1W | GWN00HDJ | GWN00LDM | GWN00MH9 | GWN00P52 |
| GWN00E26 | GWN00G1Y | GWN00HDK | GWN00LDN | GWN00MHA | GWN00P53 |
| GWN00E28 | GWN00G20 | GWN00HDL | GWN00LDP | GWN00MHC | GWN00P54 |
| GWN00E29 | GWN00G21 | GWN00HDM | GWN00LDR | GWN00N9C | GWN00P55 |
| GWN00E2A | GWN00G22 | GWN00HDN | GWN00LDT | GWN00N9D | GWN00P56 |
| GWN00E2C | GWN00G23 | GWN00HDP | GWN00LDV | GWN00N9E | GWN00P57 |
| GWN00E2D | GWN00G24 | GWN00HDR | GWN00LDW | GWN00N9F | GWN00P58 |
| GWN00E2E | GWN00G25 | GWN00HDT | GWN00LDY | GWN00N9G | GWN00P59 |
| GWN00E2F | GWN00G26 | GWN00HDV | GWN00LE0 | GWN00N9H | GWN00P5A |
| GWN00E2G | GWN00G27 | GWN00HDW | GWN00LE1 | GWN00N9J | GWN00P5C |
| GWN00E2H | GWN00G28 | GWN00HDY | GWN00LE2 | GWN00N9K | GWN00P5D |
| GWN00E2J | GWN00G29 | GWN00HE0 | GWN00LE3 | GWN00N9L | GWN00P5E |
| GWN00ENL | GWN00G2A | GWN00HE1 | GWN00LE4 | GWN00N9M | GWN00P5F |
| GWN00ENM | GWN00G2C | GWN00HE2 | GWN00LE5 | GWN00N9N | GWN00P5G |
| GWN00ENN | GWN00GNJ | GWN00HE3 | GWN00LE6 | GWN00N9P | GWN00P5H |
| GWN00ENP | GWN00GNK | GWN00HE4 | GWN00LE7 | GWN00N9R | GWN00P5J |
| GWN00ENR | GWN00GNL | GWN00HE5 | GWN00LE8 | GWN00N9T | GWN00P5K |
| GWN00ENT | GWN00GNM | GWN00HE6 | GWN00LE9 | GWN00N9V | GWN00P5L |
| GWN00ENV | GWN00GNN | GWN00HE7 | GWN00LR0 | GWN00P23 | GWN00P5M |
| GWN00ENW | GWN00GNP | GWN00HE8 | GWN00LR1 | GWN00P24 | GWN00P5N |
| GWN00ENY | GWN00GNR | GWN00JNK | GWN00LR2 | GWN00P25 | GWN00PFV |
| GWN00EP0 | GWN00GNT | GWN00JNL | GWN00LR3 | GWN00P26 | GWN00PP2 |
| GWN00EP1 | GWN00GNV | GWN00JNM | GWN00LR4 | GWN00P45 | GWN00PP3 |
| GWN00EP2 | GWN00GNW | GWN00JNN | GWN00LR5 | GWN00P46 | GWN00PP4 |
| GWN00EP3 | GWN00GNY | GWN00JNP | GWN00LR6 | GWN00P47 | GWN00PP5 |
| GWN00EP4 | GWN00GP0 | GWN00JNR | GWN00LR7 | GWN00P48 | GWN00PP6 |
| GWN00EP5 | GWN00GP1 | GWN00JNT | GWN00LR8 | GWN00P49 | GWN00PP7 |
| GWN00FD1 | GWN00GP2 | GWN00JNV | GWN00LR9 | GWN00P4A | GWN00PP8 |
| GWN00FD2 | GWN00GP3 | GWN00JNW | GWN00LRA | GWN00P4C | GWN00PP9 |
| GWN00FD3 | GWN00GP4 | GWN00JNY | GWN00LRC | GWN00P4D | GWN00PPA |
| GWN00FD4 | GWN00HD1 | GWN00JP0 | GWN00LRD | GWN00P4E | GWN00PPC |
| GWN00FD5 | GWN00HD2 | GWN00JP1 | GWN00LRE | GWN00P4G | GWN00PPD |
| GWN00FD6 | GWN00HD3 | GWN00JP2 | GWN00LRF | GWN00P4H | GWN00PPE |
| GWN00FD7 | GWN00HD4 | GWN00JP3 | GWN00LRG | GWN00P4J | GWN00PPF |
| GWN00FD8 | GWN00HD5 | GWN00LD8 | GWN00MGT | GWN00P4K | GWN00PPG |
| GWN00FD9 | GWN00HD6 | GWN00LD9 | GWN00MGV | GWN00P4L | GWN00PPH |
| GWN00FDA | GWN00HD7 | GWN00LDA | GWN00MGW | GWN00P4M | GWN00PPJ |
| GWN00FDC | GWN00HD8 | GWN00LDC | GWN00MGY | GWN00P4N | GWN00PPK |
| GWN00FDD | GWN00HD9 | GWN00LDD | GWN00MH0 | GWN00P4P | GWN00PPL |
| GWN00FDE | GWN00HDA | GWN00LDE | GWN00MH1 | GWN00P4R | GWN00PPM |
| GWN00FDF | GWN00HDC | GWN00LDF | GWN00MH2 | GWN00P4T | GWN00RA7 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN00RA8 | GWN00VL4 | GWN00YEV | GWN010MR | GWN01270 | GWN01480 |
| GWN00RA9 | GWN00VL5 | GWN00YEW | GWN01181 | GWN01271 | GWN01481 |
| GWN00RAA | GWN00VL6 | GWN00YEY | GWN01182 | GWN01272 | GWN0148M |
| GWN00RAC | GWN00VL7 | GWN00YF0 | GWN01183 | GWN01273 | GWN0148N |
| GWN00RAD | GWN00VL8 | GWN00YF1 | GWN01184 | GWN012NT | GWN0148P |
| GWN00RAE | GWN00VL9 | GWN00YF2 | GWN01185 | GWN012NV | GWN014LG |
| GWN00RAF | GWN00VLA | GWN00YF3 | GWN01186 | GWN012NW | GWN014LH |
| GWN00RAG | GWN00VLC | GWN00YF4 | GWN01187 | GWN012NY | GWN014LJ |
| GWN00RAH | GWN00YDF | GWN00YF5 | GWN01188 | GWN012P0 | GWN014LK |
| GWN00RAK | GWN00YDG | GWN00YF7 | GWN01189 | GWN012P1 | GWN014LL |
| GWN00RAL | GWN00YDH | GWN00YF8 | GWN0118A | GWN012P2 | GWN014LM |
| GWN00TFH | GWN00YDJ | GWN00YF9 | GWN0118C | GWN012P3 | GWN014LN |
| GWN00TFJ | GWN00YDK | GWN00YFA | GWN0118D | GWN012P4 | GWN014LP |
| GWN00TFK | GWN00YDL | GWN00YFC | GWN0118E | GWN012P5 | GWN014LR |
| GWN00TFL | GWN00YDM | GWN00YFD | GWN011E3 | GWN012P6 | GWN014LW |
| GWN00TFM | GWN00YDN | GWN00YFE | GWN011EN | GWN012P7 | GWN014LY |
| GWN00TFN | GWN00YDP | GWN00YFF | GWN011EP | GWN013LM | GWN014M0 |
| GWN00TFP | GWN00YDR | GWN00YFG | GWN011ER | GWN013LN | GWN014N5 |
| GWN00TFR | GWN00YDT | GWN00YFH | GWN011EV | GWN013LP | GWN014N6 |
| GWN00TFT | GWN00YDV | GWN00YFJ | GWN011F2 | GWN013LR | GWN014N7 |
| GWN00TFV | GWN00YDW | GWN00YFK | GWN011F3 | GWN013LT | GWN0154K |
| GWN00TFW | GWN00YDY | GWN00YFL | GWN011F4 | GWN013LV | GWN0154L |
| GWN00TFY | GWN00YE0 | GWN00YFM | GWN011F5 | GWN013LW | GWN01591 |
| GWN00TG0 | GWN00YE1 | GWN00YFN | GWN011F6 | GWN013LY | GWN01592 |
| GWN00TG1 | GWN00YE2 | GWN00YFP | GWN011F7 | GWN013M0 | GWN01593 |
| GWN00TG2 | GWN00YE3 | GWN0108P | GWN01206 | GWN013M1 | GWN01594 |
| GWN00TG3 | GWN00YE4 | GWN0108R | GWN01207 | GWN013M2 | GWN01595 |
| GWN00TG4 | GWN00YE5 | GWN0108T | GWN01208 | GWN013M3 | GWN01596 |
| GWN00TG5 | GWN00YE6 | GWN0108V | GWN01209 | GWN013M4 | GWN01597 |
| GWN00TG6 | GWN00YE7 | GWN0108Y | GWN0120A | GWN013M5 | GWN01598 |
| GWN00TG7 | GWN00YE8 | GWN01090 | GWN0120C | GWN013M6 | GWN01599 |
| GWN00TG8 | GWN00YE9 | GWN01091 | GWN0120D | GWN013M7 | GWN0159A |
| GWN00TG9 | GWN00YEA | GWN01092 | GWN0120E | GWN013M8 | GWN0159C |
| GWN00TGA | GWN00YEC | GWN01093 | GWN0120F | GWN013M9 | GWN0159D |
| GWN00V3M | GWN00YED | GWN01094 | GWN0120G | GWN013MA | GWN0159E |
| GWN00V3N | GWN00YEE | GWN01095 | GWN0120H | GWN013MC | GWN0159F |
| GWN00VKP | GWN00YEF | GWN01096 | GWN0120J | GWN013MD | GWN0159G |
| GWN00VKR | GWN00YEG | GWN01097 | GWN0120K | GWN013ME | GWN0159H |
| GWN00VKT | GWN00YEH | GWN01098 | GWN0120L | GWN013MF | GWN0159J |
| GWN00VKV | GWN00YEJ | GWN01099 | GWN0120M | GWN013MG | GWN0159K |
| GWN00VKW | GWN00YEK | GWN010MJ | GWN0126P | GWN0147P | GWN0159L |
| GWN00VKY | GWN00YEM | GWN010MK | GWN0126R | GWN0147R | GWN0159M |
| GWN00VL0 | GWN00YEN | GWN010ML | GWN0126T | GWN0147T | GWN0159N |
| GWN00VL1 | GWN00YEP | GWN010MM | GWN0126V | GWN0147V | GWN0159P |
| GWN00VL2 | GWN00YER | GWN010MN | GWN0126W | GWN0147W | GWN0159R |
| GWN00VL3 | GWN00YET | GWN010MP | GWN0126Y | GWN0147Y | GWN0159T |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN01647 | GWN019CF | GWN019H0 | GWN01C3Y | GWN01CKC | GWN01F22 |
| GWN01648 | GWN019CG | GWN019H1 | GWN01C40 | GWN01CKD | GWN01F23 |
| GWN016V4 | GWN019CH | GWN019H2 | GWN01C41 | GWN01CKE | GWN01F24 |
| GWN016V5 | GWN019CJ | GWN019H3 | GWN01C42 | GWN01CKF | GWN01F25 |
| GWN016V6 | GWN019CK | GWN019H4 | GWN01C43 | GWN01CKG | GWN01F26 |
| GWN016V7 | GWN019CL | GWN019H5 | GWN01C44 | GWN01CKH | GWN01F27 |
| GWN016V8 | GWN019CM | GWN019H6 | GWN01C45 | GWN01CKJ | GWN01F28 |
| GWN016V9 | GWN019CN | GWN019H7 | GWN01C46 | GWN01CKK | GWN01F29 |
| GWN016VA | GWN019CP | GWN019H8 | GWN01C47 | GWN01CKL | GWN01F2A |
| GWN016VC | GWN019CR | GWN019H9 | GWN01C48 | GWN01CKM | GWN01F2C |
| GWN016VD | GWN019CT | GWN019HA | GWN01C49 | GWN01CKN | GWN01F2D |
| GWN0178D | GWN019CV | GWN019HC | GWN01C4A | GWN01CKP | GWN01F2E |
| GWN0178E | GWN019CW | GWN019HD | GWN01C4C | GWN01DJY | GWN01F2F |
| GWN0178F | GWN019CY | GWN019HE | GWN01C4D | GWN01DK0 | GWN01FNT |
| GWN0178G | GWN019D0 | GWN019HF | GWN01C4E | GWN01DK1 | GWN01FNV |
| GWN017PR | GWN019D1 | GWN019HG | GWN01C4F | GWN01DK2 | GWN01FNW |
| GWN017PT | GWN019D2 | GWN019HH | GWN01C4G | GWN01DK3 | GWN01FNY |
| GWN017PW | GWN019D3 | GWN019PW | GWN01C4H | GWN01DK4 | GWN01FP0 |
| GWN017PY | GWN019D4 | GWN019PY | GWN01C4J | GWN01DK5 | GWN01FP1 |
| GWN017R0 | GWN019D5 | GWN019R0 | GWN01C4K | GWN01DK6 | GWN01FP2 |
| GWN017R1 | GWN019D6 | GWN019R1 | GWN01C4L | GWN01DK7 | GWN01FP3 |
| GWN017R2 | GWN019D7 | GWN019R2 | GWN01C4M | GWN01DK8 | GWN01FP4 |
| GWN017R3 | GWN019D8 | GWN019R3 | GWN01C4N | GWN01DK9 | GWN01FP5 |
| GWN018W7 | GWN019G5 | GWN019R4 | GWN01C4P | GWN01DKA | GWN01FP6 |
| GWN018W8 | GWN019G6 | GWN019R5 | GWN01C4R | GWN01DKC | GWN01FP7 |
| GWN018W9 | GWN019G7 | GWN019R6 | GWN01C4T | GWN01DKD | GWN01FP8 |
| GWN018WA | GWN019G8 | GWN019R7 | GWN01C4V | GWN01DKE | GWN01FP9 |
| GWN018WC | GWN019G9 | GWN019R8 | GWN01C4W | GWN01DKF | GWN01FPA |
| GWN01961 | GWN019GA | GWN019R9 | GWN01C4Y | GWN01EET | GWN01FPC |
| GWN01962 | GWN019GC | GWN019RA | GWN01C50 | GWN01EEV | GWN01FPD |
| GWN01963 | GWN019GD | GWN019RC | GWN01C51 | GWN01EEW | GWN01GKD |
| GWN01964 | GWN019GE | GWN01C3D | GWN01C52 | GWN01EEY | GWN01GKE |
| GWN01965 | GWN019GF | GWN01C3E | GWN01C53 | GWN01EF0 | GWN01GKF |
| GWN01966 | GWN019GG | GWN01C3F | GWN01C54 | GWN01EF1 | GWN01GKG |
| GWN01967 | GWN019GH | GWN01C3G | GWN01C55 | GWN01EF2 | GWN01GKH |
| GWN01968 | GWN019GJ | GWN01C3H | GWN01C56 | GWN01EF3 | GWN01GKJ |
| GWN01969 | GWN019GK | GWN01C3J | GWN01C57 | GWN01EF5 | GWN01GKK |
| GWN019C4 | GWN019GL | GWN01C3K | GWN01C58 | GWN01EF6 | GWN01GKL |
| GWN019C5 | GWN019GM | GWN01C3L | GWN01C59 | GWN01EF7 | GWN01GKM |
| GWN019C6 | GWN019GN | GWN01C3M | GWN01CK4 | GWN01EF8 | GWN01GKN |
| GWN019C7 | GWN019GP | GWN01C3N | GWN01CK5 | GWN01EF9 | GWN01GKP |
| GWN019C8 | GWN019GR | GWN01C3P | GWN01CK6 | GWN01EFA | GWN01GKR |
| GWN019C9 | GWN019GT | GWN01C3R | GWN01CK7 | GWN01EFC | GWN01GKT |
| GWN019CA | GWN019GV | GWN01C3T | GWN01CK8 | GWN01F1W | GWN01GKV |
| GWN019CC | GWN019GW | GWN01C3V | GWN01CK9 | GWN01F1Y | GWN01GKW |
| GWN019CE | GWN019GY | GWN01C3W | GWN01CKA | GWN01F21 | GWN01GKY |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN01GL0 | GWN022D7 | GWN025K0 | GWN028FT | GWN02A9M | GWN02CR0 |
| GWN01GL1 | GWN022D8 | GWN025K1 | GWN028FW | GWN02A9N | GWN02CR1 |
| GWN01W3T | GWN022D9 | GWN025K2 | GWN028G0 | GWN02A9P | GWN02CR2 |
| GWN01W3W | GWN022E5 | GWN025K3 | GWN028G1 | GWN02A9R | GWN02CR3 |
| GWN01W40 | GWN022EP | GWN025K4 | GWN028J7 | GWN02A9T | GWN02CR4 |
| GWN01W41 | GWN0239K | GWN025K5 | GWN028J8 | GWN02A9W | GWN02CR5 |
| GWN01W42 | GWN0239L | GWN025K6 | GWN028J9 | GWN02AA1 | GWN02CR6 |
| GWN02044 | GWN0239M | GWN025K7 | GWN028JA | GWN02AA5 | GWN02CR7 |
| GWN02045 | GWN0239N | GWN025K8 | GWN028JC | GWN02AA8 | GWN02CR8 |
| GWN02046 | GWN0239P | GWN025K9 | GWN028JD | GWN02AAC | GWN02CR9 |
| GWN02047 | GWN0239R | GWN025KA | GWN028JE | GWN02AAF | GWN02CRA |
| GWN02048 | GWN0239T | GWN025KC | GWN028JF | GWN02AAM | GWN02DHD |
| GWN02049 | GWN0239W | GWN025KD | GWN028JG | GWN02AAR | GWN02DHE |
| GWN0204D | GWN023A0 | GWN0270T | GWN028JH | GWN02AAT | GWN02DHF |
| GWN0204F | GWN023A1 | GWN0270W | GWN028JJ | GWN02AAW | GWN02DHG |
| GWN0204G | GWN023A2 | GWN02710 | GWN028JK | GWN02AC2 | GWN02DHH |
| GWN0204H | GWN023A3 | GWN02711 | GWN028JL | GWN02AC3 | GWN02DHJ |
| GWN0204K | GWN023A4 | GWN02712 | GWN028JM | GWN02ACT | GWN02DHK |
| GWN0204L | GWN023A5 | GWN02713 | GWN028JP | GWN02APD | GWN02DHL |
| GWN0204M | GWN0243G | GWN02714 | GWN028JR | GWN02APE | GWN02DHM |
| GWN0204N | GWN0243H | GWN02715 | GWN028JT | GWN02APF | GWN02DHN |
| GWN0204P | GWN0243J | GWN02716 | GWN028JW | GWN02APG | GWN02DHP |
| GWN020T8 | GWN0243K | GWN02717 | GWN028K0 | GWN02APH | GWN02DHR |
| GWN020T9 | GWN0243L | GWN02718 | GWN028K2 | GWN02APJ | GWN02DHW |
| GWN020TA | GWN0243M | GWN02719 | GWN028TR | GWN02APK | GWN02DLG |
| GWN020TC | GWN0243N | GWN0271A | GWN028TT | GWN02APL | GWN02DLJ |
| GWN020TD | GWN0243P | GWN0271C | GWN028TW | GWN02APM | GWN02FL7 |
| GWN020TE | GWN0243R | GWN0271E | GWN028W0 | GWN02C8G | GWN02FL8 |
| GWN020TF | GWN0243T | GWN0271F | GWN028W1 | GWN02C8H | GWN02FL9 |
| GWN020TG | GWN0243W | GWN0271G | GWN028W2 | GWN02C8J | GWN02FLA |
| GWN020TH | GWN02440 | GWN0271H | GWN028W3 | GWN02C8K | GWN02FLC |
| GWN020TJ | GWN02441 | GWN0271J | GWN028W4 | GWN02C8L | GWN02FLD |
| GWN020TK | GWN0246J | GWN02779 | GWN028W5 | GWN02C8M | GWN02FLE |
| GWN020TL | GWN0246K | GWN0277A | GWN028W6 | GWN02C8N | GWN02FLF |
| GWN022CM | GWN0246L | GWN0277C | GWN028W7 | GWN02C8P | GWN02FLG |
| GWN022CN | GWN0246N | GWN0277D | GWN0297E | GWN02C8R | GWN02FLH |
| GWN022CP | GWN0246P | GWN02890 | GWN0297F | GWN02C8T | GWN02FLJ |
| GWN022CR | GWN0246R | GWN028FG | GWN0297G | GWN02C8W | GWN02FLK |
| GWN022CW | GWN0246T | GWN028FH | GWN0297H | GWN02CPJ | GWN02FLL |
| GWN022D0 | GWN0246W | GWN028FJ | GWN0297J | GWN02CPL | GWN02FLM |
| GWN022D1 | GWN02470 | GWN028FK | GWN0297K | GWN02CPM | GWN02FLP |
| GWN022D2 | GWN02471 | GWN028FL | GWN0297L | GWN02CPN | GWN02FLR |
| GWN022D3 | GWN02472 | GWN028FM | GWN0297N | GWN02CPP | GWN02FLT |
| GWN022D4 | GWN02473 | GWN028FN | GWN0297P | GWN02CPR | GWN02FLW |
| GWN022D5 | GWN025CC | GWN028FP | GWN02A9K | GWN02CPT | GWN02FM0 |
| GWN022D6 | GWN025CD | GWN028FR | GWN02A9L | GWN02CPW | GWN02FM1 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN02FM2 | GWN02HL1 | GWN02L18 | GWN02MCJ | GWN02PEC | GWN02W6A |
| GWN02FM3 | GWN02HL2 | GWN02L1A | GWN02MCK | GWN02PED | GWN02W6C |
| GWN02FM4 | GWN02HL3 | GWN02L1C | GWN02MCL | GWN02PEE | GWN02W6D |
| GWN02FM5 | GWN02HL4 | GWN02L1D | GWN02MCM | GWN02PEF | GWN02W6E |
| GWN02FM6 | GWN02HL5 | GWN02L1G | GWN02MCN | GWN02RHP | GWN02W6F |
| GWN02FM7 | GWN02HL6 | GWN02L1H | GWN02MCP | GWN02RHR | GWN02W6G |
| GWN02FM8 | GWN02HL7 | GWN02L1J | GWN02MCR | GWN02RHT | GWN02W6H |
| GWN02GJ0 | GWN02HL8 | GWN02LJ7 | GWN02MCT | GWN02RHW | GWN02W6J |
| GWN02GJ1 | GWN02HL9 | GWN02LJ8 | GWN02NG6 | GWN02RJ0 | GWN02W6K |
| GWN02GJ2 | GWN02J8N | GWN02LJ9 | GWN02NG7 | GWN02RJ1 | GWN02W6L |
| GWN02GJ4 | GWN02JC2 | GWN02LJA | GWN02NG8 | GWN02RJ2 | GWN03001 |
| GWN02GJ5 | GWN02K0L | GWN02LJC | GWN02NG9 | GWN02RJ3 | GWN03002 |
| GWN02GJ6 | GWN02K0M | GWN02LJD | GWN02NGA | GWN02RJ4 | GWN03003 |
| GWN02GJ7 | GWN02K0N | GWN02LJE | GWN02NGC | GWN02RJ5 | GWN03004 |
| GWN02GJ9 | GWN02K0P | GWN02LJF | GWN02NGD | GWN02RJ6 | GWN03005 |
| GWN02GJA | GWN02K0R | GWN02LJG | GWN02NGE | GWN02RJ7 | GWN03006 |
| GWN02GJC | GWN02K0T | GWN02LJH | GWN02NGF | GWN02RJ8 | GWN03007 |
| GWN02GJD | GWN02K0W | GWN02LJJ | GWN02NGG | GWN02RJ9 | GWN03008 |
| GWN02GJE | GWN02K10 | GWN02LJK | GWN02NGH | GWN02RJC | GWN03009 |
| GWN02GJF | GWN02K11 | GWN02LJL | GWN02NGJ | GWN02RJE | GWN0300A |
| GWN02GJG | GWN02K12 | GWN02LJM | GWN02NGK | GWN02RJF | GWN0300C |
| GWN02GJJ | GWN02K13 | GWN02LJN | GWN02NGL | GWN02RJH | GWN030LM |
| GWN02GJK | GWN02K14 | GWN02LJP | GWN02NGM | GWN02RJJ | GWN030LN |
| GWN02GJL | GWN02K15 | GWN02LJR | GWN02NGN | GWN02RJL | GWN030LP |
| GWN02GJM | GWN02K16 | GWN02LJT | GWN02NGP | GWN02T5K | GWN030LR |
| GWN02GJN | GWN02K17 | GWN02LJW | GWN02NGR | GWN02T5L | GWN030LT |
| GWN02GJP | GWN02K19 | GWN02LK0 | GWN02NGT | GWN02T5M | GWN030LW |
| GWN02GJR | GWN02K1A | GWN02LK1 | GWN02P7J | GWN02T5N | GWN030M0 |
| GWN02GJT | GWN02K1C | GWN02LK2 | GWN02P7K | GWN02T5P | GWN030M1 |
| GWN02GJW | GWN02K1D | GWN02LK3 | GWN02P7L | GWN02T5R | GWN030M2 |
| GWN02GK0 | GWN02K1E | GWN02LK4 | GWN02P7M | GWN02T5T | GWN031J2 |
| GWN02GK1 | GWN02K1F | GWN02MC1 | GWN02PDN | GWN02T5W | GWN031J5 |
| GWN02GK2 | GWN02L0G | GWN02MC2 | GWN02PDP | GWN02T60 | GWN031J6 |
| GWN02GK3 | GWN02L0J | GWN02MC3 | GWN02PDR | GWN02T61 | GWN031J7 |
| GWN02GK4 | GWN02L0K | GWN02MC4 | GWN02PDT | GWN02T62 | GWN031J8 |
| GWN02GK5 | GWN02L0L | GWN02MC5 | GWN02PDW | GWN02T63 | GWN031J9 |
| GWN02GK6 | GWN02L0N | GWN02MC6 | GWN02PE0 | GWN02T64 | GWN031JA |
| GWN02GK7 | GWN02L0P | GWN02MC7 | GWN02PE1 | GWN02T65 | GWN031JC |
| GWN02GK8 | GWN02L0R | GWN02MC8 | GWN02PE2 | GWN02T66 | GWN031JD |
| GWN02GK9 | GWN02L0W | GWN02MC9 | GWN02PE4 | GWN02T67 | GWN031JE |
| GWN02GKA | GWN02L10 | GWN02MCA | GWN02PE5 | GWN02T68 | GWN031JF |
| GWN02GKC | GWN02L11 | GWN02MCC | GWN02PE6 | GWN02T69 | GWN031JG |
| GWN02GKD | GWN02L13 | GWN02MCD | GWN02PE7 | GWN02T6A | GWN031JH |
| GWN02GKE | GWN02L14 | GWN02MCE | GWN02PE8 | GWN02T6C | GWN031JK |
| GWN02HKW | GWN02L16 | GWN02MCG | GWN02PE9 | GWN02W68 | GWN031JL |
| GWN02HL0 | GWN02L17 | GWN02MCH | GWN02PEA | GWN02W69 | GWN031JM |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN031JN | GWN03462 | GWN03679 | GWN03896 | GWN03A55 | GWN03CPH |
| GWN031JP | GWN03463 | GWN0367A | GWN03897 | GWN03A56 | GWN03CPJ |
| GWN031JR | GWN03464 | GWN0367C | GWN03898 | GWN03C1D | GWN03CPL |
| GWN0329A | GWN03465 | GWN0367D | GWN03899 | GWN03C1E | GWN03CPM |
| GWN0329C | GWN03466 | GWN0367E | GWN038NE | GWN03C1F | GWN03CPP |
| GWN0329D | GWN03467 | GWN0367F | GWN038NF | GWN03C1G | GWN03CPT |
| GWN0329E | GWN03468 | GWN0367J | GWN038NG | GWN03C1H | GWN03CR1 |
| GWN0329F | GWN03469 | GWN0367K | GWN038NH | GWN03C1J | GWN03CR3 |
| GWN0329G | GWN0346A | GWN0367L | GWN038NJ | GWN03C1K | GWN03CR4 |
| GWN0329H | GWN0346C | GWN0367M | GWN038NK | GWN03C1L | GWN03CR5 |
| GWN0329J | GWN0346D | GWN0367N | GWN038NL | GWN03C1M | GWN03CR6 |
| GWN0329K | GWN0346E | GWN03737 | GWN038NM | GWN03C1N | GWN03DT3 |
| GWN0329L | GWN0346F | GWN03738 | GWN038NN | GWN03C1P | GWN03DT4 |
| GWN0329M | GWN0346G | GWN03739 | GWN038NP | GWN03C1R | GWN03DT5 |
| GWN0329N | GWN0346H | GWN0373A | GWN038NR | GWN03C1T | GWN03DT6 |
| GWN0329P | GWN0346J | GWN0373C | GWN038NT | GWN03C1W | GWN03DT7 |
| GWN0329R | GWN0346K | GWN0373D | GWN038NW | GWN03C20 | GWN03DT8 |
| GWN0329T | GWN0346L | GWN0373E | GWN038P0 | GWN03C21 | GWN03DT9 |
| GWN0329W | GWN0346M | GWN0373F | GWN038P1 | GWN03C22 | GWN03DTA |
| GWN032A0 | GWN03541 | GWN0373G | GWN038P2 | GWN03C24 | GWN03DTC |
| GWN032A1 | GWN03542 | GWN0373H | GWN038P3 | GWN03C25 | GWN03EE7 |
| GWN032A2 | GWN03543 | GWN0373J | GWN038P4 | GWN03CMM | GWN03EEM |
| GWN032A3 | GWN03544 | GWN0373K | GWN038P9 | GWN03CMW | GWN03EEN |
| GWN032A4 | GWN03545 | GWN0373L | GWN039R8 | GWN03CN2 | GWN03EEP |
| GWN0333A | GWN03546 | GWN0373M | GWN039RC | GWN03CN5 | GWN03EER |
| GWN0333C | GWN03547 | GWN0373N | GWN039RE | GWN03CN6 | GWN03EET |
| GWN0333D | GWN03548 | GWN0373P | GWN039RF | GWN03CN7 | GWN03EEW |
| GWN0333K | GWN03549 | GWN0373R | GWN039RG | GWN03CN8 | GWN03EF0 |
| GWN0333N | GWN0354A | GWN0373T | GWN039RH | GWN03CN9 | GWN03EF1 |
| GWN03340 | GWN0354C | GWN0373W | GWN039RJ | GWN03CNA | GWN03EF2 |
| GWN03348 | GWN0354D | GWN03740 | GWN039RK | GWN03CNC | GWN03EF3 |
| GWN0334C | GWN0354F | GWN0388J | GWN039RL | GWN03CND | GWN03EF4 |
| GWN0334F | GWN0354H | GWN0388K | GWN039RM | GWN03CNE | GWN03EF5 |
| GWN0334G | GWN0354J | GWN0388L | GWN039RN | GWN03CNF | GWN03EF6 |
| GWN0334H | GWN0354K | GWN0388M | GWN039RP | GWN03CNH | GWN03EF8 |
| GWN0334J | GWN0354L | GWN0388N | GWN039RR | GWN03CNJ | GWN03EF9 |
| GWN0334K | GWN0354M | GWN0388P | GWN039RT | GWN03CNL | GWN03EFA |
| GWN0334M | GWN0354N | GWN0388R | GWN039RW | GWN03CNM | GWN03F3G |
| GWN0334N | GWN03671 | GWN0388T | GWN039T0 | GWN03CNN | GWN03F3H |
| GWN0334R | GWN03672 | GWN0388W | GWN039T1 | GWN03CNR | GWN03F3J |
| GWN03359 | GWN03673 | GWN03890 | GWN039T2 | GWN03CNT | GWN03F3K |
| GWN0335A | GWN03674 | GWN03891 | GWN03A50 | GWN03CP0 | GWN03F3L |
| GWN0335C | GWN03675 | GWN03892 | GWN03A51 | GWN03CP1 | GWN03F3M |
| GWN0345W | GWN03676 | GWN03893 | GWN03A52 | GWN03CP2 | GWN03F3N |
| GWN03460 | GWN03677 | GWN03894 | GWN03A53 | GWN03CP4 | GWN03F3P |
| GWN03461 | GWN03678 | GWN03895 | GWN03A54 | GWN03CP5 | GWN03F3R |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN03F3T | GWN03HWH | GWN03KW4 | GWN03N7A | GWN03R80 | GWN03WFJ |
| GWN03F3W | GWN03HWJ | GWN03KW5 | GWN03N7C | GWN03R81 | GWN03WFK |
| GWN03F40 | GWN03HWK | GWN03KW6 | GWN03N7D | GWN03R82 | GWN03WFL |
| GWN03F41 | GWN03HWL | GWN03KW7 | GWN03N7E | GWN03R84 | GWN03WFM |
| GWN03F42 | GWN03HWM | GWN03KW8 | GWN03N7F | GWN03R85 | GWN03WFN |
| GWN03F43 | GWN03HWN | GWN03KW9 | GWN03N7G | GWN03R86 | GWN03WFP |
| GWN03F44 | GWN03HWP | GWN03KWA | GWN03N7H | GWN03R87 | GWN03WFR |
| GWN03F45 | GWN03J02 | GWN03KWC | GWN03N7J | GWN03R88 | GWN03WFT |
| GWN03F46 | GWN03J03 | GWN03KWD | GWN03NJE | GWN03R89 | GWN03WFW |
| GWN03G7H | GWN03J04 | GWN03KWE | GWN03NJF | GWN03R8A | GWN03WG0 |
| GWN03G7J | GWN03J05 | GWN03KWF | GWN03NJG | GWN03R8C | GWN03WG1 |
| GWN03G7K | GWN03J06 | GWN03KWG | GWN03NJH | GWN03R8D | GWN03WG2 |
| GWN03G7L | GWN03J07 | GWN03KWH | GWN03NJJ | GWN03R8E | GWN03WG3 |
| GWN03G7M | GWN03J08 | GWN03KWK | GWN03NJK | GWN03R8F | GWN03WG4 |
| GWN03G7N | GWN03J09 | GWN03KWL | GWN03NJL | GWN03R8G | GWN03WG5 |
| GWN03G7P | GWN03J0C | GWN03KWM | GWN03NJM | GWN03RJ6 | GWN03WG6 |
| GWN03G7R | GWN03J0D | GWN03KWN | GWN03NJN | GWN03RJ7 | GWN03WG7 |
| GWN03G7T | GWN03J0E | GWN03LW1 | GWN03NJP | GWN03RJ8 | GWN03WG8 |
| GWN03G7W | GWN03J0F | GWN03LWG | GWN03NJR | GWN03RJ9 | GWN03WG9 |
| GWN03G80 | GWN03J0G | GWN03LWH | GWN03NJT | GWN03RJA | GWN0410A |
| GWN03G81 | GWN03J0H | GWN03LWJ | GWN03NJW | GWN03T8R | GWN0410C |
| GWN03G82 | GWN03J0J | GWN03LWK | GWN03NK0 | GWN03T8W | GWN0410D |
| GWN03G84 | GWN03J9E | GWN03LWL | GWN03NK1 | GWN03T90 | GWN0410E |
| GWN03G85 | GWN03J9F | GWN03LWM | GWN03R0C | GWN03T91 | GWN0410F |
| GWN03G86 | GWN03KHD | GWN03LWN | GWN03R0G | GWN03WE7 | GWN0410G |
| GWN03G87 | GWN03KHF | GWN03LWP | GWN03R0J | GWN03WE8 | GWN0410H |
| GWN03G88 | GWN03KHG | GWN03LWR | GWN03R0K | GWN03WE9 | GWN0410J |
| GWN03G89 | GWN03KHH | GWN03LWT | GWN03R0L | GWN03WEA | GWN0410K |
| GWN03G8A | GWN03KHJ | GWN03LWW | GWN03R0N | GWN03WEC | GWN0410L |
| GWN03H96 | GWN03KHK | GWN03M00 | GWN03R0P | GWN03WED | GWN0410M |
| GWN03H97 | GWN03KHL | GWN03M01 | GWN03R0W | GWN03WEE | GWN0410N |
| GWN03HLD | GWN03KHM | GWN03M02 | GWN03R10 | GWN03WEF | GWN0410P |
| GWN03HLE | GWN03KHN | GWN03M03 | GWN03R12 | GWN03WEG | GWN0410R |
| GWN03HLF | GWN03KHP | GWN03M04 | GWN03R13 | GWN03WEH | GWN0410T |
| GWN03HLG | GWN03KHR | GWN03M05 | GWN03R14 | GWN03WEK | GWN0410W |
| GWN03HLH | GWN03KHT | GWN03M06 | GWN03R15 | GWN03WF6 | GWN04110 |
| GWN03HLJ | GWN03KHW | GWN03M07 | GWN03R16 | GWN03WF7 | GWN041KP |
| GWN03HLK | GWN03KJ0 | GWN03MEG | GWN03R17 | GWN03WF8 | GWN041KR |
| GWN03HLL | GWN03KJ1 | GWN03MEH | GWN03R7J | GWN03WF9 | GWN041KT |
| GWN03HLM | GWN03KJ2 | GWN03N72 | GWN03R7K | GWN03WFA | GWN041KW |
| GWN03HLN | GWN03KJ3 | GWN03N74 | GWN03R7M | GWN03WFC | GWN041L0 |
| GWN03HLP | GWN03KJ4 | GWN03N75 | GWN03R7N | GWN03WFD | GWN041L1 |
| GWN03HLR | GWN03KJ5 | GWN03N76 | GWN03R7P | GWN03WFE | GWN041L2 |
| GWN03HLT | GWN03KW1 | GWN03N77 | GWN03R7R | GWN03WFF | GWN041N7 |
| GWN03HLW | GWN03KW2 | GWN03N78 | GWN03R7T | GWN03WFG | GWN041N8 |
| GWN03HM0 | GWN03KW3 | GWN03N79 | GWN03R7W | GWN03WFH | GWN041N9 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN041NA | GWN04367 | GWN0470C | GWN047L4 | GWN04AM5 | GWN04CKR |
| GWN041NC | GWN04368 | GWN0470D | GWN047L5 | GWN04AM6 | GWN04CKT |
| GWN041ND | GWN04369 | GWN0470E | GWN047L6 | GWN04AM7 | GWN04CKW |
| GWN041NE | GWN0436A | GWN0470F | GWN047L7 | GWN04AM8 | GWN04CL0 |
| GWN041NF | GWN0436D | GWN0470G | GWN047L8 | GWN04AM9 | GWN04D5A |
| GWN041NG | GWN0436E | GWN0470H | GWN047L9 | GWN04AMA | GWN04D5C |
| GWN041NH | GWN043F1 | GWN047E2 | GWN047LA | GWN04AMC | GWN04D5D |
| GWN041NJ | GWN043F2 | GWN047E3 | GWN047LC | GWN04AMD | GWN04D5E |
| GWN041NK | GWN043F3 | GWN047E4 | GWN047LD | GWN04AME | GWN04D5F |
| GWN041NL | GWN043F4 | GWN047E5 | GWN047LE | GWN04AMF | GWN04D5G |
| GWN041NM | GWN043F5 | GWN047E6 | GWN047LF | GWN04AMG | GWN04D5H |
| GWN041NN | GWN043F6 | GWN047E7 | GWN048D4 | GWN04AMH | GWN04D5J |
| GWN041NP | GWN043F7 | GWN047E8 | GWN048D5 | GWN04AMJ | GWN04D5K |
| GWN041NR | GWN043F9 | GWN047E9 | GWN048D6 | GWN04AMK | GWN04D5L |
| GWN041NT | GWN043FA | GWN047EA | GWN048D7 | GWN04AML | GWN04D5M |
| GWN041NW | GWN043FD | GWN047EC | GWN048D8 | GWN04AMM | GWN04D5N |
| GWN041P0 | GWN043FE | GWN047ED | GWN048D9 | GWN04AMN | GWN04D5P |
| GWN041P1 | GWN043FF | GWN047EE | GWN048DA | GWN04AMP | GWN04D5R |
| GWN041P2 | GWN043FG | GWN047EF | GWN048DC | GWN04AMR | GWN04D5T |
| GWN042JT | GWN043FH | GWN047EG | GWN048DD | GWN04AMT | GWN04D5W |
| GWN042JW | GWN043GF | GWN047EH | GWN048DE | GWN04AMW | GWN04D60 |
| GWN042K0 | GWN04678 | GWN047EJ | GWN04990 | GWN04AN0 | GWN04D61 |
| GWN042K1 | GWN04679 | GWN047EK | GWN04A8D | GWN04AN1 | GWN04D62 |
| GWN042K2 | GWN0467A | GWN047EL | GWN04A8E | GWN04AN2 | GWN04D63 |
| GWN042K3 | GWN0467C | GWN047EM | GWN04A8F | GWN04AN3 | GWN04D64 |
| GWN042K4 | GWN0467D | GWN047EN | GWN04A8G | GWN04AN6 | GWN04D65 |
| GWN042K5 | GWN0467E | GWN047KA | GWN04A8H | GWN04AN7 | GWN04D66 |
| GWN042K6 | GWN046D5 | GWN047KC | GWN04A8K | GWN04AN8 | GWN04D67 |
| GWN042K7 | GWN046D7 | GWN047KD | GWN04A8L | GWN04ANA | GWN04D68 |
| GWN042K8 | GWN046D9 | GWN047KE | GWN04AC3 | GWN04CC5 | GWN04D69 |
| GWN042K9 | GWN046DD | GWN047KF | GWN04AC4 | GWN04CC6 | GWN04D6A |
| GWN042KA | GWN046E1 | GWN047KG | GWN04AC5 | GWN04CC7 | GWN04DCD |
| GWN042KC | GWN046E4 | GWN047KH | GWN04AC6 | GWN04CC8 | GWN04DCE |
| GWN042KD | GWN046ET | GWN047KJ | GWN04AC7 | GWN04CC9 | GWN04DNC |
| GWN042KE | GWN046EW | GWN047KK | GWN04AC8 | GWN04CCA | GWN04DND |
| GWN042KG | GWN046F0 | GWN047KL | GWN04ACJ | GWN04CCC | GWN04DNE |
| GWN042KH | GWN046F1 | GWN047KM | GWN04ACK | GWN04CJK | GWN04DNF |
| GWN042KJ | GWN046F2 | GWN047KN | GWN04ACL | GWN04CK0 | GWN04DNG |
| GWN042KK | GWN046F3 | GWN047KP | GWN04ACM | GWN04CK4 | GWN04DNH |
| GWN042KL | GWN04704 | GWN047KR | GWN04ACN | GWN04CK7 | GWN04DNJ |
| GWN042KM | GWN04705 | GWN047KT | GWN04ACP | GWN04CKC | GWN04DNK |
| GWN042KN | GWN04706 | GWN047KW | GWN04ACR | GWN04CKF | GWN04DNL |
| GWN042KP | GWN04707 | GWN047L0 | GWN04ACT | GWN04CKJ | GWN04DNM |
| GWN042KR | GWN04708 | GWN047L1 | GWN04ACW | GWN04CKM | GWN04DNN |
| GWN042KT | GWN04709 | GWN047L2 | GWN04AD0 | GWN04CKN | GWN04DNP |
| GWN042KW | GWN0470A | GWN047L3 | GWN04AD1 | GWN04CKP | GWN04DNR |



An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN04DNT | GWN04H74 | GWN04LPW | GWN04P7K | GWN04T7N | GWN050WG |
| GWN04EL8 | GWN04H75 | GWN04LR0 | GWN04P7L | GWN04T7P | GWN050WH |
| GWN04EL9 | GWN04H76 | GWN04LR1 | GWN04P7M | GWN04T7R | GWN050WJ |
| GWN04ELA | GWN04H77 | GWN04LR2 | GWN04P7N | GWN04T7T | GWN050WK |
| GWN04ELC | GWN04H78 | GWN04LR5 | GWN04P7P | GWN04TRC | GWN050WM |
| GWN04ELD | GWN04H79 | GWN04LR7 | GWN04P7R | GWN04TRD | GWN050WN |
| GWN04ELE | GWN04H7A | GWN04LR8 | GWN04P7T | GWN04TRE | GWN050WP |
| GWN04ELF | GWN04H7C | GWN04LR9 | GWN04PAC | GWN04TRF | GWN050WR |
| GWN04ELG | GWN04J9A | GWN04LRC | GWN04PAD | GWN04TRG | GWN050WT |
| GWN04ELH | GWN04J9C | GWN04LRE | GWN04PAE | GWN04W35 | GWN050WW |
| GWN04ELJ | GWN04J9D | GWN04LRG | GWN04PAF | GWN04W38 | GWN05100 |
| GWN04EN1 | GWN04J9E | GWN04LRJ | GWN04PFL | GWN04W3D | GWN05101 |
| GWN04ERK | GWN04J9F | GWN04LRK | GWN04PFM | GWN04W3E | GWN05102 |
| GWN04ERL | GWN04J9G | GWN04LRL | GWN04PFN | GWN04W3F | GWN05103 |
| GWN04FT8 | GWN04J9H | GWN04LRM | GWN04PFP | GWN04W3G | GWN05104 |
| GWN04FT9 | GWN04J9J | GWN04LRN | GWN04PFR | GWN04W3H | GWN05105 |
| GWN04FTA | GWN04J9K | GWN04LRP | GWN04PFT | GWN04W3J | GWN05106 |
| GWN04FTC | GWN04J9L | GWN04LRR | GWN04PFW | GWN04W3K | GWN051MJ |
| GWN04FTD | GWN04J9M | GWN04LRT | GWN04PG0 | GWN04W3L | GWN051MK |
| GWN04FTE | GWN04J9N | GWN04LRW | GWN04PRG | GWN04W3M | GWN051ML |
| GWN04FTF | GWN04J9P | GWN04LT0 | GWN04PRH | GWN04W3N | GWN0525N |
| GWN04FTG | GWN04J9R | GWN04LT2 | GWN04PRJ | GWN04W3P | GWN0525P |
| GWN04FTH | GWN04J9T | GWN04N1D | GWN04PRK | GWN04W3R | GWN0525R |
| GWN04GNA | GWN04J9W | GWN04N1F | GWN04PRL | GWN04W3T | GWN0525T |
| GWN04GNC | GWN04JA0 | GWN04N1H | GWN04RHL | GWN04W3W | GWN0525W |
| GWN04GND | GWN04JA1 | GWN04N1J | GWN04RHM | GWN04W40 | GWN05260 |
| GWN04GNE | GWN04LJ4 | GWN04N1L | GWN04RHN | GWN04W41 | GWN05261 |
| GWN04GNF | GWN04LJ5 | GWN04N1M | GWN04RHP | GWN04W42 | GWN05262 |
| GWN04GNG | GWN04LJ6 | GWN04N40 | GWN04RHR | GWN04W43 | GWN05263 |
| GWN04GNH | GWN04LJ7 | GWN04N41 | GWN04RW8 | GWN04WL6 | GWN05264 |
| GWN04GNJ | GWN04LJ8 | GWN04N42 | GWN04RW9 | GWN04WL7 | GWN05265 |
| GWN04GNK | GWN04LJ9 | GWN04N43 | GWN04RWA | GWN04WL8 | GWN05266 |
| GWN04GNL | GWN04LJA | GWN04N44 | GWN04RWC | GWN04WL9 | GWN052AW |
| GWN04GNM | GWN04LJC | GWN04NA6 | GWN04RWD | GWN04WLA | GWN052C0 |
| GWN04GNN | GWN04LJD | GWN04NA7 | GWN04RWE | GWN04WLD | GWN052C1 |
| GWN04GNP | GWN04LJE | GWN04NA8 | GWN04RWF | GWN04WLE | GWN052C2 |
| GWN04GNR | GWN04LPA | GWN04NA9 | GWN04RWG | GWN04WLF | GWN052C3 |
| GWN04GNT | GWN04LPC | GWN04NAA | GWN04T05 | GWN04WLG | GWN052C4 |
| GWN04GNW | GWN04LPD | GWN04P7A | GWN04T7E | GWN04WLH | GWN052C5 |
| GWN04GP0 | GWN04LPE | GWN04P7C | GWN04T7F | GWN05011 | GWN052C7 |
| GWN04GP1 | GWN04LPF | GWN04P7D | GWN04T7G | GWN05012 | GWN05337 |
| GWN04H6W | GWN04LPG | GWN04P7E | GWN04T7H | GWN05013 | GWN0537P |
| GWN04H70 | GWN04LPH | GWN04P7F | GWN04T7J | GWN050MP | GWN0537R |
| GWN04H71 | GWN04LPJ | GWN04P7G | GWN04T7K | GWN050MR | GWN0537T |
| GWN04H72 | GWN04LPN | GWN04P7H | GWN04T7L | GWN050MT | GWN0537W |
| GWN04H73 | GWN04LPR | GWN04P7J | GWN04T7M | GWN050MW | GWN05380 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN053G6 | GWN0562G | GWN05857 | GWN05APG | GWN05E9F | GWN05GTL |
| GWN053G7 | GWN0562H | GWN05858 | GWN05APH | GWN05E9G | GWN05GTN |
| GWN053G8 | GWN0562J | GWN05859 | GWN05CC9 | GWN05EE9 | GWN05GTP |
| GWN053G9 | GWN0562K | GWN0585A | GWN05CDL | GWN05EEA | GWN05HDE |
| GWN053GA | GWN0566T | GWN0585C | GWN05CDM | GWN05EEC | GWN05HDF |
| GWN053GC | GWN0566W | GWN058RA | GWN05CDN | GWN05EED | GWN05HDG |
| GWN053GD | GWN05670 | GWN058RC | GWN05CDP | GWN05EEE | GWN05HDH |
| GWN053GE | GWN05671 | GWN058RD | GWN05CDR | GWN05EEG | GWN05HDJ |
| GWN053GF | GWN05672 | GWN058RE | GWN05CDT | GWN05EMK | GWN05HDK |
| GWN053WL | GWN05673 | GWN058RF | GWN05CDW | GWN05EML | GWN05HDL |
| GWN053WN | GWN056F9 | GWN058RG | GWN05CE0 | GWN05EMN | GWN05HDM |
| GWN053WP | GWN056FA | GWN058RH | GWN05CE1 | GWN05EMP | GWN05HDN |
| GWN053WR | GWN056FC | GWN058RJ | GWN05CE2 | GWN05EMR | GWN05J19 |
| GWN053WT | GWN056FD | GWN05974 | GWN05CNK | GWN05EW2 | GWN05J1A |
| GWN053WW | GWN056JT | GWN05975 | GWN05CNL | GWN05EW3 | GWN05J1D |
| GWN05400 | GWN056JW | GWN05976 | GWN05CNM | GWN05EW4 | GWN05J1E |
| GWN05401 | GWN056K0 | GWN059J6 | GWN05CNN | GWN05EW6 | GWN05J1F |
| GWN05402 | GWN056K1 | GWN059J7 | GWN05CNP | GWN05F2F | GWN05J1G |
| GWN054LL | GWN056W4 | GWN059J8 | GWN05CNR | GWN05F2G | GWN05J1H |
| GWN054LM | GWN056W5 | GWN059J9 | GWN05CNT | GWN05F2H | GWN05JFE |
| GWN054LN | GWN056W7 | GWN059JA | GWN05CNW | GWN05F2J | GWN05JFF |
| GWN054LP | GWN056W8 | GWN059JC | GWN05CP0 | GWN05F2K | GWN05JFG |
| GWN054LR | GWN056W9 | GWN059JD | GWN05CP1 | GWN05F2L | GWN05JFH |
| GWN054LT | GWN05763 | GWN059JE | GWN05D3D | GWN05FJF | GWN05JFJ |
| GWN054LW | GWN05764 | GWN059JF | GWN05D3E | GWN05FJG | GWN05JFK |
| GWN054M0 | GWN05765 | GWN059JJ | GWN05D3F | GWN05FJJ | GWN05JFL |
| GWN054M1 | GWN05766 | GWN05A4F | GWN05D3G | GWN05FJK | GWN05JFM |
| GWN054M2 | GWN057H4 | GWN05A4G | GWN05D3H | GWN05FPC | GWN05JRE |
| GWN05507 | GWN057H5 | GWN05A4H | GWN05D3J | GWN05FPD | GWN05JRF |
| GWN05508 | GWN057H6 | GWN05A4J | GWN05D3K | GWN05FPE | GWN05JRG |
| GWN05509 | GWN057H7 | GWN05A4K | GWN05D3L | GWN05FPF | GWN05JRH |
| GWN0550A | GWN057HP | GWN05A4L | GWN05D3M | GWN05G45 | GWN05JRJ |
| GWN0557R | GWN057HR | GWN05AGJ | GWN05D3N | GWN05GD8 | GWN05K0J |
| GWN0557T | GWN05831 | GWN05AGK | GWN05DF8 | GWN05GD9 | GWN05K0K |
| GWN0557W | GWN05832 | GWN05AGL | GWN05DF9 | GWN05GDA | GWN05K0L |
| GWN05580 | GWN05833 | GWN05AGM | GWN05DFA | GWN05GDC | GWN05K7R |
| GWN05581 | GWN05834 | GWN05AGN | GWN05E7H | GWN05GDD | GWN05K7T |
| GWN05582 | GWN05835 | GWN05AGP | GWN05E7J | GWN05GE5 | GWN05K7W |
| GWN055PP | GWN0584W | GWN05AP7 | GWN05E7K | GWN05GE6 | GWN05K80 |
| GWN055PR | GWN05850 | GWN05AP8 | GWN05E7L | GWN05GE7 | GWN05K81 |
| GWN055PT | GWN05851 | GWN05AP9 | GWN05E7M | GWN05GE8 | GWN05KJ6 |
| GWN055PW | GWN05852 | GWN05APA | GWN05E7N | GWN05GE9 | GWN05KJ7 |
| GWN055R0 | GWN05853 | GWN05APC | GWN05E7P | GWN05GN1 | GWN05KJ8 |
| GWN055R1 | GWN05854 | GWN05APD | GWN05E9C | GWN05GN2 | GWN05KJ9 |
| GWN055R2 | GWN05855 | GWN05APE | GWN05E9D | GWN05GN3 | GWN05L46 |
| GWN055R3 | GWN05856 | GWN05APF | GWN05E9E | GWN05GTK | GWN05L47 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN05L48 | GWN05PMF | GWN05WW5 | GWN0622H | GWN0678W | GWN06C11 |
| GWN05LC3 | GWN05PMG | GWN05WW6 | GWN0622J | GWN06790 | GWN06C12 |
| GWN05LC4 | GWN05PMH | GWN05WW7 | GWN062PJ | GWN06791 | GWN06C13 |
| GWN05LC5 | GWN05PMJ | GWN05WW8 | GWN062PK | GWN067PK | GWN06C14 |
| GWN05LC6 | GWN05PMK | GWN05WW9 | GWN062PL | GWN067PR | GWN06C15 |
| GWN05LC7 | GWN05PML | GWN06001 | GWN062PM | GWN067R2 | GWN06C16 |
| GWN05LRC | GWN05PMM | GWN06002 | GWN062PN | GWN067R3 | GWN06C17 |
| GWN05LRD | GWN05R85 | GWN06003 | GWN0633R | GWN067R4 | GWN06C18 |
| GWN05LRE | GWN05R86 | GWN06004 | GWN0633T | GWN067RT | GWN06C19 |
| GWN05LRF | GWN05R87 | GWN06005 | GWN0633W | GWN0686C | GWN06CGA |
| GWN05LRG | GWN05R89 | GWN06006 | GWN06340 | GWN0686D | GWN06CGC |
| GWN05M32 | GWN05R8C | GWN06007 | GWN06341 | GWN0686E | GWN06CGD |
| GWN05M33 | GWN05R8D | GWN0606R | GWN06342 | GWN0686F | GWN06CGE |
| GWN05M34 | GWN05RR0 | GWN0606T | GWN06343 | GWN0686G | GWN06CGF |
| GWN05M35 | GWN05RR3 | GWN060F2 | GWN06375 | GWN0686H | GWN06CGG |
| GWN05M36 | GWN05RR5 | GWN060F3 | GWN06376 | GWN0686J | GWN06CGH |
| GWN05M66 | GWN05RR6 | GWN060F4 | GWN06377 | GWN0686K | GWN06CGJ |
| GWN05M67 | GWN05RR7 | GWN060F5 | GWN06378 | GWN0686L | GWN06CGK |
| GWN05M68 | GWN05T1T | GWN060F6 | GWN06379 | GWN0693C | GWN06CGL |
| GWN05M69 | GWN05T1W | GWN060L4 | GWN0637A | GWN0693D | GWN06CGM |
| GWN05M6A | GWN05T20 | GWN060L5 | GWN0637C | GWN0693E | GWN06CGN |
| GWN05MAM | GWN05T21 | GWN060L6 | GWN0637D | GWN0693F | GWN06CGP |
| GWN05MAN | GWN05T22 | GWN060L7 | GWN0637E | GWN0693G | GWN06CGR |
| GWN05MAP | GWN05T23 | GWN06122 | GWN0637F | GWN069LR | GWN06D84 |
| GWN05MAR | GWN05TFW | GWN06123 | GWN0637G | GWN069LT | GWN06D85 |
| GWN05MAT | GWN05TG0 | GWN06124 | GWN0637H | GWN069LW | GWN06D86 |
| GWN05MAW | GWN05TG1 | GWN06125 | GWN0637J | GWN069M0 | GWN06D87 |
| GWN05MC0 | GWN05TG2 | GWN06126 | GWN06416 | GWN069M1 | GWN06D88 |
| GWN05MC1 | GWN05TG3 | GWN06127 | GWN06417 | GWN069M2 | GWN06D89 |
| GWN05N58 | GWN05TJ8 | GWN06128 | GWN06418 | GWN06A0K | GWN06D8A |
| GWN05N59 | GWN05TJ9 | GWN06129 | GWN06419 | GWN06A0L | GWN06DKL |
| GWN05N5A | GWN05TJA | GWN0612A | GWN066E7 | GWN06A0M | GWN06DKM |
| GWN05N5C | GWN05TJC | GWN0612C | GWN066E8 | GWN06A0N | GWN06DKN |
| GWN05N5D | GWN05TJD | GWN061N7 | GWN066E9 | GWN06ACF | GWN06DKP |
| GWN05N5E | GWN05W8K | GWN061N8 | GWN066EA | GWN06ACG | GWN06DKT |
| GWN05N5F | GWN05W8M | GWN061N9 | GWN066N1 | GWN06ACH | GWN06DKW |
| GWN05NFH | GWN05W8N | GWN061NC | GWN066N3 | GWN06ACJ | GWN06DL0 |
| GWN05NFJ | GWN05W8P | GWN061ND | GWN066N4 | GWN06ACK | GWN06DL1 |
| GWN05NFK | GWN05W8R | GWN061NE | GWN066N6 | GWN06ACL | GWN06E30 |
| GWN05NMG | GWN05W8T | GWN061NF | GWN066N7 | GWN06ACM | GWN06E31 |
| GWN05NMH | GWN05WC0 | GWN0622A | GWN066N8 | GWN06AKA | GWN06E32 |
| GWN05NMJ | GWN05WC1 | GWN0622C | GWN066N9 | GWN06AKC | GWN06E33 |
| GWN05PM3 | GWN05WC2 | GWN0622D | GWN0678N | GWN06AKD | GWN06E34 |
| GWN05PMC | GWN05WC3 | GWN0622E | GWN0678P | GWN06AKE | GWN06E35 |
| GWN05PMD | GWN05WC4 | GWN0622F | GWN0678R | GWN06AKF | GWN06E36 |
| GWN05PME | GWN05WC5 | GWN0622G | GWN0678T | GWN06AKG | GWN06E9J |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN06EJN | GWN06H6T | GWN06KM7 | GWN06NT6 | GWN06T2A | GWN071E9 |
| GWN06EJP | GWN06H6W | GWN06KMA | GWN06NT7 | GWN06T2C | GWN071EA |
| GWN06EJR | GWN06H70 | GWN06KMD | GWN06NT8 | GWN06W1K | GWN071ED |
| GWN06EJT | GWN06H71 | GWN06KME | GWN06NT9 | GWN06W1M | GWN071EE |
| GWN06EJW | GWN06H72 | GWN06KMG | GWN06NTA | GWN06W1N | GWN071EF |
| GWN06EK0 | GWN06H73 | GWN06L41 | GWN06NTC | GWN06W1P | GWN071EG |
| GWN06EK1 | GWN06HG6 | GWN06L42 | GWN06NTK | GWN06W1R | GWN071EH |
| GWN06ETF | GWN06HG7 | GWN06L43 | GWN06P5C | GWN06W1T | GWN071EJ |
| GWN06ETG | GWN06HG8 | GWN06L44 | GWN06P5D | GWN06W24 | GWN071EK |
| GWN06ETH | GWN06HG9 | GWN06L45 | GWN06P5E | GWN06W25 | GWN071EL |
| GWN06ETJ | GWN06HGA | GWN06L46 | GWN06P5F | GWN06W26 | GWN071EM |
| GWN06FJ5 | GWN06HGC | GWN06LN2 | GWN06PPK | GWN06W28 | GWN071EN |
| GWN06FJ6 | GWN06HGD | GWN06LN3 | GWN06PPL | GWN06W29 | GWN071EP |
| GWN06FJ7 | GWN06HGE | GWN06LN4 | GWN06PPM | GWN06W2A | GWN071ER |
| GWN06FJ8 | GWN06HWA | GWN06LN5 | GWN06PPN | GWN06W2C | GWN0723E |
| GWN06FJ9 | GWN06HWC | GWN06LN6 | GWN06PPP | GWN06W2D | GWN0723F |
| GWN06FJA | GWN06HWD | GWN06LWE | GWN06PPR | GWN06W2E | GWN0723G |
| GWN06FJC | GWN06HWE | GWN06LWF | GWN06PPT | GWN06WDP | GWN0723H |
| GWN06FJD | GWN06HWF | GWN06LWG | GWN06PWL | GWN06WDR | GWN0723J |
| GWN06FR6 | GWN06J4K | GWN06LWH | GWN06R77 | GWN06WDT | GWN072AF |
| GWN06FR7 | GWN06J4L | GWN06LWJ | GWN06R78 | GWN06WDW | GWN072AG |
| GWN06FR8 | GWN06J4M | GWN06LWK | GWN06R79 | GWN06WE0 | GWN072AH |
| GWN06FR9 | GWN06J4N | GWN06M6K | GWN06R7A | GWN06WE1 | GWN072AJ |
| GWN06FRA | GWN06J4P | GWN06M6L | GWN06R7C | GWN06WE2 | GWN072AK |
| GWN06FRC | GWN06J4R | GWN06M6M | GWN06R7D | GWN06WE3 | GWN072LC |
| GWN06FRD | GWN06JPE | GWN06M6N | GWN06R7E | GWN06WRJ | GWN072LD |
| GWN06G3M | GWN06JPG | GWN06MGW | GWN06R7F | GWN06WRK | GWN072LE |
| GWN06G3N | GWN06JPH | GWN06MH0 | GWN06R7H | GWN06WRL | GWN072LF |
| GWN06G3P | GWN06JPJ | GWN06MH1 | GWN06R7J | GWN06WRM | GWN072LG |
| GWN06G3R | GWN06JPK | GWN06MH2 | GWN06R7K | GWN06WRN | GWN072LH |
| GWN06G3T | GWN06K3T | GWN06MH3 | GWN06RGR | GWN0704A | GWN072LJ |
| GWN06GH4 | GWN06K40 | GWN06MH4 | GWN06RGW | GWN0704C | GWN072WK |
| GWN06GH5 | GWN06K41 | GWN06MH5 | GWN06RH0 | GWN0704D | GWN0736G |
| GWN06GH6 | GWN06K42 | GWN06N0N | GWN06RPF | GWN0704E | GWN0736H |
| GWN06GH7 | GWN06K70 | GWN06N0P | GWN06RPG | GWN0704F | GWN0736J |
| GWN06GH8 | GWN06K71 | GWN06N0R | GWN06RPH | GWN0704H | GWN0736K |
| GWN06GH9 | GWN06K72 | GWN06N0T | GWN06RPJ | GWN0704J | GWN0736L |
| GWN06GKG | GWN06K73 | GWN06N0W | GWN06RPK | GWN070A6 | GWN0736M |
| GWN06GKH | GWN06K74 | GWN06N10 | GWN06T22 | GWN070A7 | GWN0736N |
| GWN06H2A | GWN06K80 | GWN06NA4 | GWN06T23 | GWN070A8 | GWN0736P |
| GWN06H2C | GWN06K81 | GWN06NA5 | GWN06T24 | GWN070A9 | GWN0736R |
| GWN06H2D | GWN06K82 | GWN06NA6 | GWN06T25 | GWN070AA | GWN073N3 |
| GWN06H2E | GWN06K83 | GWN06NA7 | GWN06T26 | GWN070AC | GWN073N5 |
| GWN06H2F | GWN06K84 | GWN06NA8 | GWN06T27 | GWN070AD | GWN073N7 |
| GWN06H2G | GWN06K85 | GWN06NA9 | GWN06T28 | GWN071E7 | GWN073NC |
| GWN06H2H | GWN06K86 | GWN06NT5 | GWN06T29 | GWN071E8 | GWN073NF |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN073NG | GWN076N6 | GWN079F3 | GWN07DJ0 | GWN07FR2 | GWN07HM6 |
| GWN073NH | GWN076N7 | GWN079F4 | GWN07DL6 | GWN07FR3 | GWN07HM7 |
| GWN0742J | GWN076N8 | GWN079F5 | GWN07DL7 | GWN07FR5 | GWN07HM8 |
| GWN0742K | GWN076N9 | GWN079F6 | GWN07DL8 | GWN07G33 | GWN07HM9 |
| GWN0742L | GWN076NA | GWN079F7 | GWN07DL9 | GWN07G34 | GWN07HMA |
| GWN0742M | GWN076NC | GWN079F8 | GWN07DLA | GWN07G35 | GWN07HMC |
| GWN0742N | GWN076ND | GWN079F9 | GWN07DLD | GWN07G36 | GWN07J38 |
| GWN0742P | GWN076NE | GWN079FA | GWN07DLE | GWN07G37 | GWN07J39 |
| GWN074JJ | GWN076NF | GWN079FC | GWN07DLF | GWN07GF0 | GWN07J3A |
| GWN074JK | GWN076NG | GWN079FD | GWN07DLG | GWN07GF1 | GWN07J3C |
| GWN074JL | GWN0770J | GWN079FE | GWN07DLH | GWN07GF2 | GWN07JP3 |
| GWN074JN | GWN0770K | GWN079FF | GWN07DLJ | GWN07GF3 | GWN07JP4 |
| GWN074JP | GWN0770L | GWN07AE2 | GWN07DLK | GWN07GF4 | GWN07JP5 |
| GWN074JR | GWN0770M | GWN07AE3 | GWN07DLL | GWN07GF5 | GWN07JP6 |
| GWN074JT | GWN0776G | GWN07AE4 | GWN07DLM | GWN07GF6 | GWN07JP7 |
| GWN074JW | GWN077M4 | GWN07AE5 | GWN07DLN | GWN07GF7 | GWN07JP8 |
| GWN074K0 | GWN077M5 | GWN07AE6 | GWN07DRN | GWN07GF8 | GWN07K0C |
| GWN074RK | GWN077M6 | GWN07AE8 | GWN07ECL | GWN07GF9 | GWN07K0D |
| GWN074RL | GWN077M7 | GWN07AE9 | GWN07ECM | GWN07GTT | GWN07K0E |
| GWN074RM | GWN077M8 | GWN07AEA | GWN07ECN | GWN07GTW | GWN07K0F |
| GWN074RN | GWN077M9 | GWN07AEC | GWN07ECP | GWN07GW0 | GWN07K1J |
| GWN074RP | GWN077MA | GWN07AED | GWN07EME | GWN07GW1 | GWN07K1K |
| GWN074RR | GWN077MC | GWN07AEE | GWN07EMF | GWN07GW2 | GWN07K1L |
| GWN074RT | GWN077MD | GWN07AEF | GWN07EMG | GWN07GW3 | GWN07K1M |
| GWN074RW | GWN078AK | GWN07AEH | GWN07EMH | GWN07GW4 | GWN07K1N |
| GWN0757A | GWN078AL | GWN07AEN | GWN07EMJ | GWN07GW5 | GWN07K1P |
| GWN0757C | GWN078AM | GWN07C6L | GWN07EMK | GWN07GW6 | GWN07K1R |
| GWN0757D | GWN078AN | GWN07C6M | GWN07EML | GWN07GW7 | GWN07K1T |
| GWN0757E | GWN078AP | GWN07C6N | GWN07F07 | GWN07H59 | GWN07K1W |
| GWN0757F | GWN078NJ | GWN07C6R | GWN07F08 | GWN07H5A | GWN07K20 |
| GWN0757H | GWN078NK | GWN07C6T | GWN07F09 | GWN07H5C | GWN07K21 |
| GWN075M1 | GWN078NL | GWN07C6W | GWN07F0A | GWN07H5D | GWN07K22 |
| GWN075M2 | GWN078NM | GWN07C70 | GWN07F0C | GWN07H5E | GWN07K23 |
| GWN075M3 | GWN078NN | GWN07C71 | GWN07F0D | GWN07H5F | GWN07K24 |
| GWN075M4 | GWN0790N | GWN07C72 | GWN07F0E | GWN07H5G | GWN07K25 |
| GWN075M5 | GWN0790P | GWN07CT5 | GWN07F0F | GWN07H5H | GWN07KJL |
| GWN0764G | GWN0790R | GWN07CT6 | GWN07F7T | GWN07HDH | GWN07KJM |
| GWN0764H | GWN0790W | GWN07CT7 | GWN07F7W | GWN07HDJ | GWN07KJN |
| GWN0764J | GWN07917 | GWN07CT8 | GWN07F80 | GWN07HDK | GWN07KJP |
| GWN0764K | GWN0791A | GWN07CT9 | GWN07F81 | GWN07HDL | GWN07KJW |
| GWN0764L | GWN0791C | GWN07CTA | GWN07F82 | GWN07HDM | GWN07KM8 |
| GWN0764M | GWN0791D | GWN07CTC | GWN07FPR | GWN07HDN | GWN07KM9 |
| GWN0764N | GWN0791E | GWN07DHP | GWN07FPT | GWN07HM2 | GWN07KMA |
| GWN076N3 | GWN079F0 | GWN07DHR | GWN07FPW | GWN07HM3 | GWN07KMC |
| GWN076N4 | GWN079F1 | GWN07DHT | GWN07FR0 | GWN07HM4 | GWN07KMD |
| GWN076N5 | GWN079F2 | GWN07DHW | GWN07FR1 | GWN07HM5 | GWN07KME |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN07KMF | GWN07NW8 | GWN07WM4 | GWN082R2 | GWN085H6 | GWN088N6 |
| GWN07KMG | GWN07NW9 | GWN07WM5 | GWN082WG | GWN085H7 | GWN088N7 |
| GWN07L18 | GWN07PH5 | GWN07WM6 | GWN082WH | GWN085H8 | GWN088N8 |
| GWN07L19 | GWN07PH6 | GWN07WM7 | GWN082WJ | GWN085R4 | GWN088N9 |
| GWN07L1A | GWN07PH7 | GWN07WM8 | GWN082WK | GWN085R5 | GWN088NA |
| GWN07L1E | GWN07PH8 | GWN07WM9 | GWN082WL | GWN085R6 | GWN088NC |
| GWN07LH1 | GWN07PH9 | GWN0805H | GWN082WM | GWN085R7 | GWN0896G |
| GWN07LH2 | GWN07PN6 | GWN0805J | GWN082WN | GWN085R8 | GWN0896H |
| GWN07LH3 | GWN07PN7 | GWN0805K | GWN082WP | GWN085R9 | GWN0896J |
| GWN07LH4 | GWN07PN8 | GWN0805L | GWN082WR | GWN086G7 | GWN0896K |
| GWN07LH5 | GWN07PN9 | GWN0805M | GWN083KK | GWN086G8 | GWN0896L |
| GWN07LH6 | GWN07PNA | GWN0805N | GWN083KL | GWN086G9 | GWN0896M |
| GWN07M81 | GWN07PNC | GWN080C2 | GWN083KM | GWN086GA | GWN089GJ |
| GWN07M82 | GWN07R4W | GWN080C3 | GWN083KN | GWN086GC | GWN089GM |
| GWN07M83 | GWN07R50 | GWN080C4 | GWN083KP | GWN086MA | GWN089GN |
| GWN07M84 | GWN07R51 | GWN080C5 | GWN083KR | GWN086MC | GWN089GP |
| GWN07M85 | GWN07R52 | GWN080C6 | GWN083KT | GWN086MD | GWN089GR |
| GWN07M86 | GWN07R53 | GWN080C7 | GWN0840D | GWN086ME | GWN089GT |
| GWN07MFR | GWN07R54 | GWN080C8 | GWN0840E | GWN086TM | GWN089GW |
| GWN07MFT | GWN07R55 | GWN080C9 | GWN0840F | GWN086TN | GWN089H0 |
| GWN07MFW | GWN07RDE | GWN080CA | GWN0840G | GWN086TP | GWN089H1 |
| GWN07MG0 | GWN07RDF | GWN0817G | GWN0840H | GWN086TR | GWN089H2 |
| GWN07MG1 | GWN07RDG | GWN0817H | GWN084C0 | GWN086TT | GWN089H3 |
| GWN07MG2 | GWN07RDH | GWN0817J | GWN084C1 | GWN086TW | GWN089H4 |
| GWN07N8R | GWN07RDJ | GWN0817K | GWN084C2 | GWN087L9 | GWN089H5 |
| GWN07N8T | GWN07RDK | GWN0817L | GWN084C3 | GWN087LA | GWN089H6 |
| GWN07N8W | GWN07RDL | GWN0817M | GWN084C8 | GWN087LC | GWN089H7 |
| GWN07N90 | GWN07RDM | GWN0817N | GWN084FD | GWN087LD | GWN089H8 |
| GWN07N9L | GWN07RTJ | GWN0817P | GWN084FE | GWN087LE | GWN089H9 |
| GWN07N9P | GWN07RTK | GWN081LE | GWN084FF | GWN087LF | GWN089HA |
| GWN07N9R | GWN07RTM | GWN081LF | GWN084FG | GWN087LG | GWN08A0R |
| GWN07N9T | GWN07RTN | GWN081LG | GWN084FP | GWN087LH | GWN08AEN |
| GWN07N9W | GWN07RTP | GWN081LH | GWN084PT | GWN087W1 | GWN08AEP |
| GWN07NA0 | GWN07T86 | GWN082AJ | GWN084PW | GWN087W2 | GWN08AER |
| GWN07NA1 | GWN07T87 | GWN082AK | GWN084R0 | GWN087W3 | GWN08AET |
| GWN07NA4 | GWN07T88 | GWN082AL | GWN084R1 | GWN087W4 | GWN08APC |
| GWN07NA7 | GWN07W8J | GWN082AM | GWN084R3 | GWN087W5 | GWN08APE |
| GWN07NA9 | GWN07W8K | GWN082AN | GWN084R4 | GWN087W6 | GWN08APF |
| GWN07NW0 | GWN07W8L | GWN082AP | GWN0857F | GWN088J9 | GWN08APG |
| GWN07NW1 | GWN07W8M | GWN082AR | GWN0857G | GWN088JA | GWN08APH |
| GWN07NW2 | GWN07W8N | GWN082AT | GWN0857H | GWN088JC | GWN08APJ |
| GWN07NW3 | GWN07W8P | GWN082PR | GWN0857J | GWN088JD | GWN08C14 |
| GWN07NW4 | GWN07W8R | GWN082PT | GWN085H2 | GWN088JE | GWN08C15 |
| GWN07NW5 | GWN07W8T | GWN082PW | GWN085H3 | GWN088JF | GWN08C17 |
| GWN07NW6 | GWN07W8W | GWN082R0 | GWN085H4 | GWN088JG | GWN08C18 |
| GWN07NW7 | GWN07W90 | GWN082R1 | GWN085H5 | GWN088JH | GWN08C19 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN08C6J | GWN08F2N | GWN08H5P | GWN08KMN | GWN08NK2 | GWN08T4J |
| GWN08C6K | GWN08F2P | GWN08HF3 | GWN08KMP | GWN08NK3 | GWN08T4K |
| GWN08C6L | GWN08FCT | GWN08HF4 | GWN08KMR | GWN08NK4 | GWN08T4L |
| GWN08C6M | GWN08FCW | GWN08HF5 | GWN08KW7 | GWN08NK5 | GWN08T4M |
| GWN08C6N | GWN08FD0 | GWN08HF6 | GWN08KW8 | GWN08NK6 | GWN08TJ0 |
| GWN08C6P | GWN08FD1 | GWN08HF7 | GWN08KWA | GWN08NK7 | GWN08TJ1 |
| GWN08C6R | GWN08FD2 | GWN08HF8 | GWN08KWC | GWN08NK8 | GWN08TJN |
| GWN08C6T | GWN08FD3 | GWN08J0P | GWN08KWD | GWN08NK9 | GWN08TJP |
| GWN08CK9 | GWN08FJN | GWN08J0R | GWN08LAK | GWN08NKA | GWN08TJR |
| GWN08CKA | GWN08FJP | GWN08J0T | GWN08LAL | GWN08NKC | GWN08TJT |
| GWN08CKC | GWN08FJR | GWN08J0W | GWN08LAM | GWN08NKD | GWN08W82 |
| GWN08CKD | GWN08FJT | GWN08J10 | GWN08LAN | GWN08NKE | GWN08W83 |
| GWN08CKE | GWN08FJW | GWN08J11 | GWN08LAP | GWN08NKF | GWN08W84 |
| GWN08CPC | GWN08FK0 | GWN08J4D | GWN08LAR | GWN08NKG | GWN08W85 |
| GWN08CPD | GWN08FL0 | GWN08J4E | GWN08LMT | GWN08NKH | GWN08W86 |
| GWN08CPE | GWN08FL1 | GWN08J4F | GWN08LMW | GWN08NTT | GWN08W87 |
| GWN08CPF | GWN08FL2 | GWN08J4G | GWN08LN0 | GWN08NTW | GWN08WN0 |
| GWN08CPG | GWN08FL3 | GWN08J4H | GWN08LN2 | GWN08NW0 | GWN08WN1 |
| GWN08CPH | GWN08FL4 | GWN08J4J | GWN08LN3 | GWN08NW1 | GWN08WN2 |
| GWN08DD6 | GWN08FL5 | GWN08JD6 | GWN08LN4 | GWN08NW2 | GWN08WN3 |
| GWN08DD7 | GWN08FL6 | GWN08JD7 | GWN08LN5 | GWN08NW3 | GWN08WN4 |
| GWN08DD8 | GWN08G2T | GWN08JD8 | GWN08M5E | GWN08NW4 | GWN08WN5 |
| GWN08DD9 | GWN08G2W | GWN08JD9 | GWN08M5F | GWN08P31 | GWN0903K |
| GWN08DDA | GWN08G30 | GWN08JDA | GWN08M5G | GWN08P32 | GWN0903M |
| GWN08DDC | GWN08G31 | GWN08JDC | GWN08M5H | GWN08P33 | GWN0903N |
| GWN08DRF | GWN08G33 | GWN08JDD | GWN08M5J | GWN08PHA | GWN0903P |
| GWN08DRG | GWN08GHM | GWN08JND | GWN08M5K | GWN08PHC | GWN0903R |
| GWN08DRH | GWN08GHN | GWN08JNE | GWN08MR9 | GWN08PHD | GWN0903T |
| GWN08DRJ | GWN08GHP | GWN08JNF | GWN08MRA | GWN08PHE | GWN0903W |
| GWN08DRK | GWN08GHR | GWN08JNG | GWN08MRC | GWN08PHF | GWN0904A |
| GWN08DRL | GWN08GHT | GWN08JNH | GWN08MRD | GWN08PHG | GWN090D0 |
| GWN08E7J | GWN08GHW | GWN08K5M | GWN08MRE | GWN08PHH | GWN090D1 |
| GWN08E7K | GWN08GWE | GWN08K5N | GWN08MRF | GWN08R31 | GWN090D2 |
| GWN08E7L | GWN08GWF | GWN08K5P | GWN08MRG | GWN08R32 | GWN090D3 |
| GWN08E7M | GWN08GWG | GWN08K5R | GWN08MRH | GWN08R33 | GWN090D4 |
| GWN08E7N | GWN08GWH | GWN08K5T | GWN08N5N | GWN08R34 | GWN090D5 |
| GWN08E7P | GWN08GWJ | GWN08K5W | GWN08N5P | GWN08R35 | GWN090D6 |
| GWN08EK7 | GWN08GWK | GWN08KEK | GWN08N5R | GWN08R36 | GWN090G5 |
| GWN08EK8 | GWN08GWL | GWN08KER | GWN08N5T | GWN08RT8 | GWN090G6 |
| GWN08EK9 | GWN08H5F | GWN08KET | GWN08N5W | GWN08RT9 | GWN090G8 |
| GWN08EKA | GWN08H5H | GWN08KEW | GWN08N60 | GWN08RTA | GWN090GA |
| GWN08EKC | GWN08H5J | GWN08KF0 | GWN08ND5 | GWN08RTC | GWN090GE |
| GWN08F2J | GWN08H5K | GWN08KF1 | GWN08ND6 | GWN08RTD | GWN090GH |
| GWN08F2K | GWN08H5L | GWN08KMK | GWN08ND8 | GWN08RTE | GWN090K5 |
| GWN08F2L | GWN08H5M | GWN08KML | GWN08ND9 | GWN08T4G | GWN090K6 |
| GWN08F2M | GWN08H5N | GWN08KMM | GWN08NDA | GWN08T4H | GWN090K7 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWN090K8 | GWN0941K | GWN09785 | GWNDT733 | GWNDY723 | GWNGB184 |
| GWN090K9 | GWN0941L | GWN09786 | GWNDT734 | GWNDY724 | GWNGB185 |
| GWN090KA | GWN0941M | GWN09787 | GWNDT735 | GWNDY725 | GWNGB215 |
| GWN090P8 | GWN094LA | GWN0987G | GWNDT736 | GWNGA002 | GWNGB216 |
| GWN090P9 | GWN094LC | GWN0987H | GWNDT737 | GWNGA003 | GWNGB217 |
| GWN090PA | GWN094LD | GWN0987J | GWNDT738 | GWNGA004 | GWNGB218 |
| GWN09230 | GWN094LE | GWN0987K | GWNDT739 | GWNGA005 | GWNGB219 |
| GWN09231 | GWN094LF | GWN0987L | GWNDT740 | GWNGA006 | GWNGB220 |
| GWN09232 | GWN094LG | GWN0987M | GWNDT742 | GWNGA227 | GWNGB221 |
| GWN09233 | GWN094LH | GWN098A2 | GWNDT743 | GWNGA228 | GWNGB270 |
| GWN09234 | GWN094LJ | GWN098A3 | GWNDT744 | GWNGA230 | GWNGB272 |
| GWN09235 | GWN094PM | GWN098A4 | GWNDT745 | GWNGA231 | GWNGB273 |
| GWN0923C | GWN094PN | GWN098A5 | GWNDT775 | GWNGA279 | GWNGB274 |
| GWN0923D | GWN094PP | GWN098A6 | GWNDT776 | GWNGA280 | GWNGB275 |
| GWN0923E | GWN094PR | GWN098W7 | GWNDT777 | GWNGA281 | GWNGB303 |
| GWN0923F | GWN0951J | GWN098W9 | GWNDT778 | GWNGA282 | GWNGB304 |
| GWN0923G | GWN0951K | GWN098WC | GWNDY004 | GWNGA400 | GWNGB305 |
| GWN092W8 | GWN0951L | GWN098WD | GWNDY005 | GWNGA401 | GWNGB306 |
| GWN092W9 | GWN0951M | GWN0990F | GWNDY006 | GWNGA402 | GWNGB319 |
| GWN092WA | GWN0961K | GWN0990H | GWNDY007 | GWNGA403 | GWNGB460 |
| GWN092WC | GWN0961L | GWN0990J | GWNDY008 | GWNGA404 | GWNGB463 |
| GWN092WD | GWN0961M | GWN0990L | GWNDY009 | GWNGA405 | GWNGB464 |
| GWN092WE | GWN0961P | GWNDS720 | GWNDY159 | GWNGA418 | GWNGB465 |
| GWN092WF | GWN0961R | GWNDS721 | GWNDY160 | GWNGA552 | GWNGB466 |
| GWN0932N | GWN09689 | GWNDS722 | GWNDY161 | GWNGA553 | GWNGB468 |
| GWN0932P | GWN0968A | GWNDS723 | GWNDY162 | GWNGA650 | GWNGB725 |
| GWN0932R | GWN0968C | GWNDS936 | GWNDY163 | GWNGA651 | GWNGB726 |
| GWN0932T | GWN0968D | GWNDS939 | GWNDY164 | GWNGA652 | GWNGB727 |
| GWN0932W | GWN0968E | GWNDS940 | GWNDY165 | GWNGA784 | GWNGB728 |
| GWN09330 | GWN096C8 | GWNDS941 | GWNDY399 | GWNGA785 | GWNGB729 |
| GWN09331 | GWN096C9 | GWNDS942 | GWNDY400 | GWNGA786 | GWNGB730 |
| GWN0939M | GWN096CA | GWNDS943 | GWNDY401 | GWNGA787 | GWNGB731 |
| GWN0939N | GWN096CC | GWNDT256 | GWNDY402 | GWNGA788 | GWNGB732 |
| GWN0939P | GWN096CD | GWNDT257 | GWNDY403 | GWNGA898 | GWNGB733 |
| GWN0939R | GWN0971C | GWNDT258 | GWNDY404 | GWNGA899 | GWNGD021 |
| GWN0939T | GWN0971D | GWNDT259 | GWNDY405 | GWNGA900 | GWNGD022 |
| GWN0939W | GWN0971F | GWNDT260 | GWNDY406 | GWNGA901 | GWNGD023 |
| GWN093A0 | GWN0972R | GWNDT291 | GWNDY622 | GWNGB020 | GWNGD024 |
| GWN093A1 | GWN0972T | GWNDT293 | GWNDY623 | GWNGB021 | GWNGD025 |
| GWN093J1 | GWN0972W | GWNDT442 | GWNDY624 | GWNGB022 | GWNGD117 |
| GWN093J2 | GWN09730 | GWNDT443 | GWNDY625 | GWNGB024 | GWNGD118 |
| GWN093LE | GWN09731 | GWNDT444 | GWNDY626 | GWNGB025 | GWNGD119 |
| GWN093LF | GWN09732 | GWNDT729 | GWNDY627 | GWNGB026 | GWNGD120 |
| GWN093LG | GWN09782 | GWNDT730 | GWNDY628 | GWNGB027 | GWNGD121 |
| GWN093LH | GWN09783 | GWNDT731 | GWNDY629 | GWNGB028 | GWNGD122 |
| GWN0941J | GWN09784 | GWNDT732 | GWNDY722 | GWNGB183 | GWNGD123 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNGD124 | GWNGE545 | GWNGF837 | GWNGH071 | GWNGH616 | GWNGK077 |
| GWNGD270 | GWNGE546 | GWNGF838 | GWNGH072 | GWNGH962 | GWNGK078 |
| GWNGD271 | GWNGE631 | GWNGF909 | GWNGH073 | GWNGH963 | GWNGK079 |
| GWNGD272 | GWNGE632 | GWNGG015 | GWNGH074 | GWNGH964 | GWNGK110 |
| GWNGD273 | GWNGE633 | GWNGG016 | GWNGH075 | GWNGH965 | GWNGK111 |
| GWNGD274 | GWNGE634 | GWNGG017 | GWNGH076 | GWNGH966 | GWNGK112 |
| GWNGD377 | GWNGE733 | GWNGG148 | GWNGH077 | GWNGH967 | GWNGK113 |
| GWNGD378 | GWNGE748 | GWNGG149 | GWNGH078 | GWNGH968 | GWNGK114 |
| GWNGD379 | GWNGE749 | GWNGG150 | GWNGH079 | GWNGH969 | GWNGK115 |
| GWNGD441 | GWNGE750 | GWNGG151 | GWNGH080 | GWNGH970 | GWNGK116 |
| GWNGD442 | GWNGE751 | GWNGG152 | GWNGH081 | GWNGH971 | GWNGK117 |
| GWNGD443 | GWNGE752 | GWNGG153 | GWNGH082 | GWNGH972 | GWNGK118 |
| GWNGD444 | GWNGE753 | GWNGG154 | GWNGH083 | GWNGH973 | GWNGK119 |
| GWNGD445 | GWNGE754 | GWNGG157 | GWNGH135 | GWNGJ072 | GWNGK120 |
| GWNGD446 | GWNGE755 | GWNGG158 | GWNGH136 | GWNGJ073 | GWNGK121 |
| GWNGD913 | GWNGF216 | GWNGG159 | GWNGH137 | GWNGJ074 | GWNGK122 |
| GWNGD914 | GWNGF217 | GWNGG160 | GWNGH138 | GWNGJ076 | GWNGK123 |
| GWNGD916 | GWNGF218 | GWNGG161 | GWNGH139 | GWNGJ077 | GWNGK124 |
| GWNGD917 | GWNGF219 | GWNGG185 | GWNGH167 | GWNGJ108 | GWNGK125 |
| GWNGD918 | GWNGF220 | GWNGG186 | GWNGH168 | GWNGJ109 | GWNGK126 |
| GWNGD919 | GWNGF221 | GWNGG537 | GWNGH169 | GWNGJ110 | GWNGK127 |
| GWNGD920 | GWNGF222 | GWNGG607 | GWNGH170 | GWNGJ112 | GWNGK128 |
| GWNGD921 | GWNGF224 | GWNGG608 | GWNGH171 | GWNGJ124 | GWNGK129 |
| GWNGD922 | GWNGF356 | GWNGG609 | GWNGH258 | GWNGJ125 | GWNGK130 |
| GWNGD923 | GWNGF358 | GWNGG636 | GWNGH259 | GWNGJ126 | GWNGK131 |
| GWNGD924 | GWNGF359 | GWNGG637 | GWNGH260 | GWNGJ127 | GWNGK132 |
| GWNGD925 | GWNGF360 | GWNGG638 | GWNGH261 | GWNGJ282 | GWNGK133 |
| GWNGD926 | GWNGF362 | GWNGG639 | GWNGH262 | GWNGJ283 | GWNGK134 |
| GWNGD927 | GWNGF363 | GWNGG640 | GWNGH263 | GWNGJ284 | GWNGK135 |
| GWNGD928 | GWNGF523 | GWNGG641 | GWNGH340 | GWNGJ286 | GWNGK136 |
| GWNGD929 | GWNGF526 | GWNGG642 | GWNGH341 | GWNGJ367 | GWNGK274 |
| GWNGE024 | GWNGF527 | GWNGG705 | GWNGH342 | GWNGJ368 | GWNGK275 |
| GWNGE025 | GWNGF528 | GWNGG706 | GWNGH343 | GWNGJ370 | GWNGK276 |
| GWNGE026 | GWNGF529 | GWNGG707 | GWNGH344 | GWNGJ371 | GWNGK277 |
| GWNGE084 | GWNGF530 | GWNGG708 | GWNGH407 | GWNGJ414 | GWNGK280 |
| GWNGE085 | GWNGF531 | GWNGG709 | GWNGH408 | GWNGJ415 | GWNGK281 |
| GWNGE086 | GWNGF659 | GWNGG711 | GWNGH595 | GWNGJ416 | GWNGK282 |
| GWNGE123 | GWNGF826 | GWNGG712 | GWNGH596 | GWNGJ417 | GWNGK410 |
| GWNGE124 | GWNGF827 | GWNGG713 | GWNGH597 | GWNGJ418 | GWNGK411 |
| GWNGE238 | GWNGF828 | GWNGG714 | GWNGH598 | GWNGJ419 | GWNGK412 |
| GWNGE239 | GWNGF829 | GWNGG715 | GWNGH599 | GWNGK071 | GWNGK413 |
| GWNGE240 | GWNGF830 | GWNGG786 | GWNGH600 | GWNGK072 | GWNGK414 |
| GWNGE241 | GWNGF832 | GWNGG787 | GWNGH601 | GWNGK073 | GWNGK415 |
| GWNGE490 | GWNGF833 | GWNGG788 | GWNGH602 | GWNGK074 | GWNGK416 |
| GWNGE543 | GWNGF834 | GWNGG789 | GWNGH603 | GWNGK075 | GWNGK647 |
| GWNGE544 | GWNGF835 | GWNGH070 | GWNGH615 | GWNGK076 | GWNGK648 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNGK649 | GWNGL354 | GWNGM359 | GWNGN860 | GWNGP097 | GWNGP944 |
| GWNGK651 | GWNGL355 | GWNGM360 | GWNGN861 | GWNGP098 | GWNGP945 |
| GWNGK652 | GWNGL559 | GWNGN020 | GWNGN862 | GWNGP099 | GWNGP946 |
| GWNGK653 | GWNGL560 | GWNGN021 | GWNGN863 | GWNGP100 | GWNGS038 |
| GWNGK654 | GWNGL561 | GWNGN022 | GWNGN864 | GWNGP101 | GWNGS039 |
| GWNGK655 | GWNGL562 | GWNGN023 | GWNGN865 | GWNGP102 | GWNGS040 |
| GWNGK656 | GWNGL563 | GWNGN024 | GWNGN866 | GWNGP233 | GWNGS041 |
| GWNGK702 | GWNGL609 | GWNGN032 | GWNGN867 | GWNGP234 | GWNGS042 |
| GWNGK730 | GWNGL610 | GWNGN172 | GWNGN868 | GWNGP235 | GWNGS043 |
| GWNGK731 | GWNGL611 | GWNGN173 | GWNGN869 | GWNGP236 | GWNGS044 |
| GWNGK732 | GWNGL612 | GWNGN174 | GWNGN870 | GWNGP237 | GWNGS045 |
| GWNGK733 | GWNGL613 | GWNGN175 | GWNGN871 | GWNGP238 | GWNGS046 |
| GWNGK734 | GWNGL668 | GWNGN176 | GWNGN872 | GWNGP239 | GWNGS047 |
| GWNGK735 | GWNGL669 | GWNGN177 | GWNGN873 | GWNGP240 | GWNGS048 |
| GWNGK736 | GWNGL670 | GWNGN195 | GWNGN874 | GWNGP241 | GWNGS049 |
| GWNGK737 | GWNGL671 | GWNGN196 | GWNGN875 | GWNGP242 | GWNGS050 |
| GWNGK738 | GWNGL672 | GWNGN197 | GWNGN876 | GWNGP243 | GWNGS051 |
| GWNGK739 | GWNGL826 | GWNGN198 | GWNGN877 | GWNGP244 | GWNGS052 |
| GWNGK994 | GWNGL827 | GWNGN199 | GWNGN878 | GWNGP245 | GWNGS095 |
| GWNGK995 | GWNGL828 | GWNGN200 | GWNGN879 | GWNGP246 | GWNGS096 |
| GWNGK996 | GWNGL829 | GWNGN201 | GWNGN880 | GWNGP247 | GWNGS097 |
| GWNGK997 | GWNGL830 | GWNGN237 | GWNGN881 | GWNGP248 | GWNGS098 |
| GWNGK998 | GWNGL936 | GWNGN239 | GWNGN882 | GWNGP249 | GWNGS099 |
| GWNGL001 | GWNGL937 | GWNGN240 | GWNGN883 | GWNGP250 | GWNGS100 |
| GWNGL002 | GWNGL938 | GWNGN241 | GWNGN885 | GWNGP251 | GWNGS101 |
| GWNGL003 | GWNGL939 | GWNGN243 | GWNGN886 | GWNGP252 | GWNGS102 |
| GWNGL004 | GWNGL940 | GWNGN244 | GWNGN887 | GWNGP253 | GWNGS103 |
| GWNGL005 | GWNGL941 | GWNGN245 | GWNGN888 | GWNGP254 | GWNGS104 |
| GWNGL006 | GWNGL942 | GWNGN246 | GWNGN889 | GWNGP255 | GWNGS105 |
| GWNGL007 | GWNGM058 | GWNGN248 | GWNGN890 | GWNGP256 | GWNGS106 |
| GWNGL008 | GWNGM059 | GWNGN456 | GWNGN891 | GWNGP257 | GWNGS107 |
| GWNGL009 | GWNGM060 | GWNGN812 | GWNGN892 | GWNGP258 | GWNGS108 |
| GWNGL269 | GWNGM061 | GWNGN813 | GWNGN893 | GWNGP678 | GWNGS109 |
| GWNGL270 | GWNGM062 | GWNGN814 | GWNGN898 | GWNGP930 | GWNGS110 |
| GWNGL271 | GWNGM063 | GWNGN815 | GWNGN900 | GWNGP931 | GWNGS111 |
| GWNGL272 | GWNGM148 | GWNGN816 | GWNGN901 | GWNGP932 | GWNGS112 |
| GWNGL273 | GWNGM204 | GWNGN817 | GWNGN902 | GWNGP933 | GWNGS113 |
| GWNGL274 | GWNGM205 | GWNGN818 | GWNGP087 | GWNGP934 | GWNGS114 |
| GWNGL275 | GWNGM206 | GWNGN819 | GWNGP089 | GWNGP935 | GWNGS115 |
| GWNGL276 | GWNGM207 | GWNGN820 | GWNGP090 | GWNGP936 | GWNGS243 |
| GWNGL277 | GWNGM208 | GWNGN821 | GWNGP091 | GWNGP937 | GWNGS244 |
| GWNGL278 | GWNGM209 | GWNGN831 | GWNGP092 | GWNGP938 | GWNGS245 |
| GWNGL350 | GWNGM354 | GWNGN832 | GWNGP093 | GWNGP939 | GWNGS247 |
| GWNGL351 | GWNGM355 | GWNGN833 | GWNGP094 | GWNGP940 | GWNGS249 |
| GWNGL352 | GWNGM356 | GWNGN834 | GWNGP095 | GWNGP941 | GWNGS250 |
| GWNGL353 | GWNGM358 | GWNGN835 | GWNGP096 | GWNGP943 | GWNGS251 |


TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNGS252 | GWNGS621 | GWNGS984 | GWNGT370 | GWNGT609 | GWNSA017 |
| GWNGS253 | GWNGS622 | GWNGS985 | GWNGT371 | GWNGT610 | GWNSA018 |
| GWNGS254 | GWNGS623 | GWNGS986 | GWNGT372 | GWNGT611 | GWNSA019 |
| GWNGS391 | GWNGS624 | GWNGS987 | GWNGT373 | GWNGT612 | GWNSA020 |
| GWNGS392 | GWNGS625 | GWNGS988 | GWNGT374 | GWNGT613 | GWNSA021 |
| GWNGS393 | GWNGS626 | GWNGS989 | GWNGT375 | GWNGT614 | GWNSA022 |
| GWNGS394 | GWNGS627 | GWNGS990 | GWNGT434 | GWNGT615 | GWNSA023 |
| GWNGS395 | GWNGS628 | GWNGT018 | GWNGT435 | GWNGT616 | GWNSA024 |
| GWNGS396 | GWNGS629 | GWNGT019 | GWNGT436 | GWNGT617 | GWNSA026 |
| GWNGS397 | GWNGS677 | GWNGT085 | GWNGT437 | GWNGT618 | GWNSA027 |
| GWNGS398 | GWNGS678 | GWNGT086 | GWNGT438 | GWNGT619 | GWNSA028 |
| GWNGS417 | GWNGS679 | GWNGT087 | GWNGT439 | GWNGT620 | GWNSA029 |
| GWNGS418 | GWNGS680 | GWNGT088 | GWNGT441 | GWNGT664 | GWNSA030 |
| GWNGS419 | GWNGS681 | GWNGT089 | GWNGT442 | GWNGT665 | GWNSA031 |
| GWNGS420 | GWNGS682 | GWNGT090 | GWNGT445 | GWNGT666 | GWNSA032 |
| GWNGS421 | GWNGS683 | GWNGT091 | GWNGT446 | GWNGT667 | GWNSA033 |
| GWNGS422 | GWNGS684 | GWNGT092 | GWNGT447 | GWNGT668 | GWNSA034 |
| GWNGS423 | GWNGS685 | GWNGT130 | GWNGT512 | GWNGT669 | GWNSA036 |
| GWNGS424 | GWNGS686 | GWNGT198 | GWNGT513 | GWNGT670 | GWNSA037 |
| GWNGS435 | GWNGS743 | GWNGT199 | GWNGT514 | GWNGT671 | GWNSA038 |
| GWNGS450 | GWNGS744 | GWNGT200 | GWNGT515 | GWNGT672 | GWNSA039 |
| GWNGS451 | GWNGS745 | GWNGT201 | GWNGT516 | GWNGT673 | GWNSA081 |
| GWNGS452 | GWNGS746 | GWNGT202 | GWNGT517 | GWNGT674 | GWNSA082 |
| GWNGS453 | GWNGS747 | GWNGT203 | GWNGT518 | GWNGT675 | GWNSA083 |
| GWNGS454 | GWNGS748 | GWNGT205 | GWNGT519 | GWNGT676 | GWNSA084 |
| GWNGS455 | GWNGS751 | GWNGT206 | GWNGT520 | GWNGT677 | GWNSA085 |
| GWNGS456 | GWNGS771 | GWNGT207 | GWNGT521 | GWNGT775 | GWNSA086 |
| GWNGS457 | GWNGS819 | GWNGT208 | GWNGT522 | GWNGT776 | GWNSA087 |
| GWNGS458 | GWNGS820 | GWNGT209 | GWNGT523 | GWNGT777 | GWNSA088 |
| GWNGS533 | GWNGS821 | GWNGT210 | GWNGT554 | GWNGT778 | GWNSA089 |
| GWNGS534 | GWNGS822 | GWNGT211 | GWNGT555 | GWNGT779 | GWNSA090 |
| GWNGS535 | GWNGS823 | GWNGT212 | GWNGT556 | GWNGT780 | GWNSA091 |
| GWNGS536 | GWNGS824 | GWNGT213 | GWNGT557 | GWNGT781 | GWNSA092 |
| GWNGS537 | GWNGS825 | GWNGT283 | GWNGT558 | GWNGT782 | GWNSA093 |
| GWNGS538 | GWNGS826 | GWNGT284 | GWNGT559 | GWNGT783 | GWNSA094 |
| GWNGS539 | GWNGS827 | GWNGT285 | GWNGT560 | GWNGT784 | GWNSA095 |
| GWNGS540 | GWNGS974 | GWNGT286 | GWNGT561 | GWNGT785 | GWNSA096 |
| GWNGS541 | GWNGS975 | GWNGT287 | GWNGT562 | GWNGT786 | GWNSA097 |
| GWNGS542 | GWNGS976 | GWNGT288 | GWNGT563 | GWNGT787 | GWNSA098 |
| GWNGS543 | GWNGS977 | GWNGT289 | GWNGT564 | GWNGT788 | GWNSA099 |
| GWNGS544 | GWNGS978 | GWNGT290 | GWNGT565 | GWNSA011 | GWNSA100 |
| GWNGS545 | GWNGS979 | GWNGT291 | GWNGT566 | GWNSA012 | GWNSA101 |
| GWNGS547 | GWNGS980 | GWNGT366 | GWNGT591 | GWNSA013 | GWNSA102 |
| GWNGS548 | GWNGS981 | GWNGT367 | GWNGT606 | GWNSA014 | GWNSA103 |
| GWNGS549 | GWNGS982 | GWNGT368 | GWNGT607 | GWNSA015 | GWNSA104 |
| GWNGS550 | GWNGS983 | GWNGT369 | GWNGT608 | GWNSA016 | GWNSA105 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNSA106 | GWNSA628 | GWNSA867 | GWNSB143 | GWNSB434 | GWNSB704 |
| GWNSA107 | GWNSA629 | GWNSA868 | GWNSB144 | GWNSB435 | GWNSB705 |
| GWNSA108 | GWNSA630 | GWNSA869 | GWNSB145 | GWNSB436 | GWNSB706 |
| GWNSA109 | GWNSA631 | GWNSA870 | GWNSB146 | GWNSB437 | GWNSB707 |
| GWNSA110 | GWNSA632 | GWNSA871 | GWNSB147 | GWNSB438 | GWNSB708 |
| GWNSA111 | GWNSA633 | GWNSA872 | GWNSB148 | GWNSB439 | GWNSB709 |
| GWNSA114 | GWNSA634 | GWNSA873 | GWNSB149 | GWNSB440 | GWNSB710 |
| GWNSA115 | GWNSA635 | GWNSA874 | GWNSB150 | GWNSB441 | GWNSB711 |
| GWNSA116 | GWNSA636 | GWNSA875 | GWNSB151 | GWNSB442 | GWNSB712 |
| GWNSA117 | GWNSA637 | GWNSA877 | GWNSB152 | GWNSB443 | GWNSB713 |
| GWNSA118 | GWNSA638 | GWNSA878 | GWNSB153 | GWNSB444 | GWNSB714 |
| GWNSA515 | GWNSA639 | GWNSA879 | GWNSB154 | GWNSB518 | GWNSB715 |
| GWNSA516 | GWNSA640 | GWNSA880 | GWNSB155 | GWNSB519 | GWNSB716 |
| GWNSA517 | GWNSA641 | GWNSA881 | GWNSB156 | GWNSB520 | GWNSB717 |
| GWNSA518 | GWNSA642 | GWNSA882 | GWNSB157 | GWNSB521 | GWNSB760 |
| GWNSA519 | GWNSA644 | GWNSA883 | GWNSB158 | GWNSB522 | GWNSB761 |
| GWNSA520 | GWNSA645 | GWNSB003 | GWNSB159 | GWNSB523 | GWNSB762 |
| GWNSA521 | GWNSA646 | GWNSB004 | GWNSB305 | GWNSB524 | GWNSB763 |
| GWNSA522 | GWNSA647 | GWNSB005 | GWNSB306 | GWNSB525 | GWNSB764 |
| GWNSA523 | GWNSA648 | GWNSB006 | GWNSB307 | GWNSB526 | GWNSB765 |
| GWNSA524 | GWNSA750 | GWNSB007 | GWNSB308 | GWNSB527 | GWNSB766 |
| GWNSA525 | GWNSA751 | GWNSB008 | GWNSB309 | GWNSB528 | GWNSB767 |
| GWNSA526 | GWNSA752 | GWNSB009 | GWNSB310 | GWNSB529 | GWNSB768 |
| GWNSA527 | GWNSA753 | GWNSB010 | GWNSB311 | GWNSB530 | GWNSB769 |
| GWNSA528 | GWNSA754 | GWNSB011 | GWNSB312 | GWNSB531 | GWNSB770 |
| GWNSA530 | GWNSA755 | GWNSB012 | GWNSB313 | GWNSB532 | GWNSB771 |
| GWNSA531 | GWNSA757 | GWNSB122 | GWNSB314 | GWNSB533 | GWNSB772 |
| GWNSA532 | GWNSA847 | GWNSB123 | GWNSB315 | GWNSB534 | GWNSB773 |
| GWNSA533 | GWNSA848 | GWNSB124 | GWNSB316 | GWNSB535 | GWNSB774 |
| GWNSA534 | GWNSA849 | GWNSB125 | GWNSB317 | GWNSB537 | GWNSB775 |
| GWNSA535 | GWNSA850 | GWNSB126 | GWNSB318 | GWNSB538 | GWNSB776 |
| GWNSA537 | GWNSA851 | GWNSB127 | GWNSB319 | GWNSB570 | GWNSB777 |
| GWNSA538 | GWNSA852 | GWNSB128 | GWNSB320 | GWNSB571 | GWNSB778 |
| GWNSA539 | GWNSA853 | GWNSB129 | GWNSB321 | GWNSB572 | GWNSB779 |
| GWNSA540 | GWNSA854 | GWNSB130 | GWNSB322 | GWNSB573 | GWNSB852 |
| GWNSA541 | GWNSA855 | GWNSB131 | GWNSB323 | GWNSB574 | GWNSB853 |
| GWNSA542 | GWNSA856 | GWNSB132 | GWNSB324 | GWNSB575 | GWNSB854 |
| GWNSA543 | GWNSA857 | GWNSB133 | GWNSB424 | GWNSB576 | GWNSB855 |
| GWNSA544 | GWNSA858 | GWNSB134 | GWNSB425 | GWNSB628 | GWNSB857 |
| GWNSA545 | GWNSA859 | GWNSB135 | GWNSB426 | GWNSB629 | GWNSB858 |
| GWNSA546 | GWNSA860 | GWNSB136 | GWNSB427 | GWNSB698 | GWNSB859 |
| GWNSA623 | GWNSA862 | GWNSB137 | GWNSB428 | GWNSB699 | GWNSB860 |
| GWNSA624 | GWNSA863 | GWNSB138 | GWNSB430 | GWNSB700 | GWNSB861 |
| GWNSA625 | GWNSA864 | GWNSB139 | GWNSB431 | GWNSB701 | GWNSB862 |
| GWNSA626 | GWNSA865 | GWNSB140 | GWNSB432 | GWNSB702 | GWNSB863 |
| GWNSA627 | GWNSA866 | GWNSB141 | GWNSB433 | GWNSB703 | GWNSB864 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNSB865 | GWNSC077 | GWNSC262 | GWNSC454 | GWNSC573 | GWNSC850 |
| GWNSB866 | GWNSC078 | GWNSC263 | GWNSC455 | GWNSC574 | GWNSC851 |
| GWNSB867 | GWNSC079 | GWNSC264 | GWNSC456 | GWNSC575 | GWNSC852 |
| GWNSB868 | GWNSC080 | GWNSC265 | GWNSC457 | GWNSC576 | GWNSC853 |
| GWNSB869 | GWNSC081 | GWNSC266 | GWNSC458 | GWNSC577 | GWNSC854 |
| GWNSB870 | GWNSC082 | GWNSC267 | GWNSC459 | GWNSC578 | GWNSC870 |
| GWNSB871 | GWNSC083 | GWNSC268 | GWNSC460 | GWNSC579 | GWNSC871 |
| GWNSB872 | GWNSC084 | GWNSC269 | GWNSC461 | GWNSC580 | GWNSC926 |
| GWNSB910 | GWNSC085 | GWNSC271 | GWNSC462 | GWNSC581 | GWNSC927 |
| GWNSB911 | GWNSC086 | GWNSC344 | GWNSC463 | GWNSC626 | GWNSC928 |
| GWNSB932 | GWNSC087 | GWNSC345 | GWNSC464 | GWNSC627 | GWNSC929 |
| GWNSB933 | GWNSC088 | GWNSC346 | GWNSC465 | GWNSC628 | GWNSC930 |
| GWNSB934 | GWNSC089 | GWNSC347 | GWNSC466 | GWNSC629 | GWNSC931 |
| GWNSB935 | GWNSC090 | GWNSC348 | GWNSC467 | GWNSC630 | GWNSC932 |
| GWNSB936 | GWNSC091 | GWNSC349 | GWNSC468 | GWNSC631 | GWNSC933 |
| GWNSB937 | GWNSC093 | GWNSC350 | GWNSC469 | GWNSC632 | GWNSC934 |
| GWNSB938 | GWNSC094 | GWNSC351 | GWNSC470 | GWNSC633 | GWNSC935 |
| GWNSB939 | GWNSC095 | GWNSC353 | GWNSC471 | GWNSC634 | GWNSC936 |
| GWNSB941 | GWNSC096 | GWNSC354 | GWNSC502 | GWNSC635 | GWNSC937 |
| GWNSB943 | GWNSC097 | GWNSC356 | GWNSC503 | GWNSC709 | GWNSC938 |
| GWNSB945 | GWNSC233 | GWNSC357 | GWNSC504 | GWNSC710 | GWNSC939 |
| GWNSB946 | GWNSC234 | GWNSC358 | GWNSC505 | GWNSC711 | GWNSC940 |
| GWNSB947 | GWNSC235 | GWNSC359 | GWNSC506 | GWNSC712 | GWNSC941 |
| GWNSB948 | GWNSC236 | GWNSC360 | GWNSC507 | GWNSC713 | GWNSC942 |
| GWNSB949 | GWNSC237 | GWNSC361 | GWNSC508 | GWNSC714 | GWNSC943 |
| GWNSB950 | GWNSC238 | GWNSC362 | GWNSC509 | GWNSC715 | GWNSC945 |
| GWNSB951 | GWNSC240 | GWNSC363 | GWNSC510 | GWNSC716 | GWNSC946 |
| GWNSC058 | GWNSC241 | GWNSC435 | GWNSC511 | GWNSC717 | GWNSC947 |
| GWNSC059 | GWNSC242 | GWNSC436 | GWNSC512 | GWNSC718 | GWNSC948 |
| GWNSC060 | GWNSC243 | GWNSC437 | GWNSC513 | GWNSC719 | GWNSC949 |
| GWNSC061 | GWNSC244 | GWNSC438 | GWNSC514 | GWNSC720 | GWNSC950 |
| GWNSC062 | GWNSC245 | GWNSC439 | GWNSC515 | GWNSC721 | GWNSC951 |
| GWNSC063 | GWNSC246 | GWNSC440 | GWNSC516 | GWNSC836 | GWNSC952 |
| GWNSC064 | GWNSC247 | GWNSC441 | GWNSC517 | GWNSC837 | GWNSC953 |
| GWNSC065 | GWNSC248 | GWNSC442 | GWNSC518 | GWNSC838 | GWNSC954 |
| GWNSC066 | GWNSC249 | GWNSC443 | GWNSC561 | GWNSC839 | GWNSD209 |
| GWNSC067 | GWNSC250 | GWNSC444 | GWNSC562 | GWNSC840 | GWNSD210 |
| GWNSC068 | GWNSC252 | GWNSC445 | GWNSC563 | GWNSC841 | GWNSD211 |
| GWNSC069 | GWNSC253 | GWNSC446 | GWNSC564 | GWNSC842 | GWNSD212 |
| GWNSC070 | GWNSC254 | GWNSC447 | GWNSC565 | GWNSC843 | GWNSD213 |
| GWNSC071 | GWNSC256 | GWNSC448 | GWNSC566 | GWNSC844 | GWNSD214 |
| GWNSC072 | GWNSC257 | GWNSC449 | GWNSC567 | GWNSC845 | GWNSD215 |
| GWNSC073 | GWNSC258 | GWNSC450 | GWNSC568 | GWNSC846 | GWNSD216 |
| GWNSC074 | GWNSC259 | GWNSC451 | GWNSC569 | GWNSC847 | GWNSD217 |
| GWNSC075 | GWNSC260 | GWNSC452 | GWNSC570 | GWNSC848 | GWNSD218 |
| GWNSC076 | GWNSC261 | GWNSC453 | GWNSC571 | GWNSC849 | GWNSD219 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNSD220 | GWNSD290 | GWNSD525 | GWNSD957 | GWNSE005 | GWNSE314 |
| GWNSD221 | GWNSD291 | GWNSD526 | GWNSD958 | GWNSE006 | GWNSE315 |
| GWNSD222 | GWNSD309 | GWNSD527 | GWNSD959 | GWNSE136 | GWNSE316 |
| GWNSD223 | GWNSD310 | GWNSD528 | GWNSD960 | GWNSE137 | GWNSE317 |
| GWNSD224 | GWNSD311 | GWNSD529 | GWNSD961 | GWNSE138 | GWNSE318 |
| GWNSD225 | GWNSD312 | GWNSD530 | GWNSD962 | GWNSE139 | GWNSE319 |
| GWNSD226 | GWNSD313 | GWNSD531 | GWNSD963 | GWNSE140 | GWNSE320 |
| GWNSD227 | GWNSD314 | GWNSD532 | GWNSD964 | GWNSE141 | GWNSE321 |
| GWNSD228 | GWNSD315 | GWNSD533 | GWNSD965 | GWNSE142 | GWNSE322 |
| GWNSD229 | GWNSD316 | GWNSD534 | GWNSD966 | GWNSE143 | GWNSE323 |
| GWNSD230 | GWNSD317 | GWNSD535 | GWNSD967 | GWNSE144 | GWNSE324 |
| GWNSD231 | GWNSD318 | GWNSD536 | GWNSD968 | GWNSE145 | GWNSE325 |
| GWNSD233 | GWNSD319 | GWNSD537 | GWNSD969 | GWNSE146 | GWNSE326 |
| GWNSD234 | GWNSD320 | GWNSD538 | GWNSD970 | GWNSE147 | GWNSE327 |
| GWNSD257 | GWNSD321 | GWNSD741 | GWNSD971 | GWNSE148 | GWNSE328 |
| GWNSD258 | GWNSD322 | GWNSD742 | GWNSD972 | GWNSE149 | GWNSE329 |
| GWNSD259 | GWNSD323 | GWNSD743 | GWNSD973 | GWNSE150 | GWNSE330 |
| GWNSD260 | GWNSD324 | GWNSD744 | GWNSD974 | GWNSE151 | GWNSE395 |
| GWNSD261 | GWNSD343 | GWNSD745 | GWNSD975 | GWNSE152 | GWNSE419 |
| GWNSD262 | GWNSD344 | GWNSD746 | GWNSD976 | GWNSE284 | GWNSE420 |
| GWNSD263 | GWNSD346 | GWNSD747 | GWNSD977 | GWNSE285 | GWNSE421 |
| GWNSD264 | GWNSD490 | GWNSD748 | GWNSD978 | GWNSE286 | GWNSE422 |
| GWNSD265 | GWNSD491 | GWNSD749 | GWNSD979 | GWNSE287 | GWNSE423 |
| GWNSD266 | GWNSD492 | GWNSD750 | GWNSD980 | GWNSE288 | GWNSE424 |
| GWNSD267 | GWNSD494 | GWNSD751 | GWNSD981 | GWNSE289 | GWNSE425 |
| GWNSD268 | GWNSD495 | GWNSD752 | GWNSD982 | GWNSE290 | GWNSE426 |
| GWNSD269 | GWNSD496 | GWNSD753 | GWNSD983 | GWNSE291 | GWNSE427 |
| GWNSD270 | GWNSD497 | GWNSD755 | GWNSD984 | GWNSE292 | GWNSE428 |
| GWNSD271 | GWNSD498 | GWNSD756 | GWNSD985 | GWNSE294 | GWNSE429 |
| GWNSD272 | GWNSD499 | GWNSD757 | GWNSD986 | GWNSE295 | GWNSE430 |
| GWNSD273 | GWNSD500 | GWNSD758 | GWNSD987 | GWNSE296 | GWNSE431 |
| GWNSD274 | GWNSD501 | GWNSD759 | GWNSD988 | GWNSE297 | GWNSE432 |
| GWNSD276 | GWNSD502 | GWNSD760 | GWNSD989 | GWNSE298 | GWNSE433 |
| GWNSD277 | GWNSD503 | GWNSD761 | GWNSD990 | GWNSE299 | GWNSE434 |
| GWNSD278 | GWNSD504 | GWNSD770 | GWNSD991 | GWNSE300 | GWNSE435 |
| GWNSD279 | GWNSD505 | GWNSD946 | GWNSD992 | GWNSE301 | GWNSE436 |
| GWNSD280 | GWNSD506 | GWNSD947 | GWNSD993 | GWNSE302 | GWNSE437 |
| GWNSD281 | GWNSD507 | GWNSD948 | GWNSD994 | GWNSE303 | GWNSE438 |
| GWNSD282 | GWNSD508 | GWNSD949 | GWNSD995 | GWNSE304 | GWNSE439 |
| GWNSD283 | GWNSD509 | GWNSD950 | GWNSD996 | GWNSE305 | GWNSE440 |
| GWNSD284 | GWNSD519 | GWNSD951 | GWNSD997 | GWNSE306 | GWNSE443 |
| GWNSD285 | GWNSD520 | GWNSD952 | GWNSD998 | GWNSE307 | GWNSE445 |
| GWNSD286 | GWNSD521 | GWNSD953 | GWNSE001 | GWNSE308 | GWNSE446 |
| GWNSD287 | GWNSD522 | GWNSD954 | GWNSE002 | GWNSE309 | GWNSE447 |
| GWNSD288 | GWNSD523 | GWNSD955 | GWNSE003 | GWNSE310 | GWNSE448 |
| GWNSD289 | GWNSD524 | GWNSD956 | GWNSE004 | GWNSE312 | GWNSE449 |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

| | | | | | |
|---|---|---|---|---|---|
| GWNSE450 | GWNSE543 | GWNSE759 | GWNSE781 | GWNSE931 | GWNSE953 |
| GWNSE522 | GWNSE544 | GWNSE760 | GWNSE782 | GWNSE932 | GWNSE954 |
| GWNSE523 | GWNSE545 | GWNSE761 | GWNSE783 | GWNSE933 | GWNSE955 |
| GWNSE524 | GWNSE546 | GWNSE762 | GWNSE784 | GWNSE934 | GWNSE956 |
| GWNSE525 | GWNSE547 | GWNSE763 | GWNSE785 | GWNSE935 | GWNSE957 |
| GWNSE526 | GWNSE548 | GWNSE764 | GWNSE786 | GWNSE936 | GWNSE958 |
| GWNSE527 | GWNSE549 | GWNSE765 | GWNSE787 | GWNSE937 | GWNSE959 |
| GWNSE528 | GWNSE550 | GWNSE766 | GWNSE788 | GWNSE938 | GWNSE960 |
| GWNSE529 | GWNSE551 | GWNSE767 | GWNSE887 | GWNSE939 | GWNSE961 |
| GWNSE530 | GWNSE552 | GWNSE768 | GWNSE888 | GWNSE940 | GWNSE962 |
| GWNSE531 | GWNSE553 | GWNSE769 | GWNSE889 | GWNSE941 | GWNSE963 |
| GWNSE532 | GWNSE554 | GWNSE770 | GWNSE890 | GWNSE942 | GWNSE964 |
| GWNSE533 | GWNSE555 | GWNSE771 | GWNSE891 | GWNSE943 | GWNSE965 |
| GWNSE534 | GWNSE750 | GWNSE772 | GWNSE892 | GWNSE944 | GWNSE966 |
| GWNSE535 | GWNSE751 | GWNSE773 | GWNSE893 | GWNSE945 | GWNSE967 |
| GWNSE536 | GWNSE752 | GWNSE774 | GWNSE894 | GWNSE946 | GWNSE968 |
| GWNSE537 | GWNSE753 | GWNSE775 | GWNSE896 | GWNSE947 | GWNSE969 |
| GWNSE538 | GWNSE754 | GWNSE776 | GWNSE897 | GWNSE948 | |
| GWNSE539 | GWNSE755 | GWNSE777 | GWNSE898 | GWNSE949 | |
| GWNSE540 | GWNSE756 | GWNSE778 | GWNSE899 | GWNSE950 | |
| GWNSE541 | GWNSE757 | GWNSE779 | GWNSE929 | GWNSE951 | |
| GWNSE542 | GWNSE758 | GWNSE780 | GWNSE930 | GWNSE952 | |

An agency of the European Union

TE.CAP.00110-009 © European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified.
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.