AD/DH 104/31 Drag Bracing Member, Centre Section Spar Lower Boom - Inspection and Replacement 5/73

Applicability: All models.

Document: Hawker Siddeley TNS CT(104) No. 230.

Compliance:

1. Inspect fittings in accordance with para. 4 of TNS CT(104) No. 230 within 100 hours time in service after 29 June 1973 or before 1 August 1973 whichever occurs first.

2. Replace fittings in accordance with para. 5 of TNS CT(104) No. 230 before 1 July 1974.