AD/DH 104/26 Rudder Control Pedal Reversal Lever - Inspection 2/71

Applicability: All models.

Document: Hawker Siddeley TNS CT(104) No. 219.

Compliance: Within 100 hours time in service after 31 March 1971 and thereafter at intervals not exceeding 2400 hours time in service.