AD/DH 104/29 Engine Mounting Frame - Inspection 5/72

Applicability: All models.

Document: Hawker Siddeley TNS CT(104) No. 228 Issue 1.

Compliance: Within 50 hours time in service after 22 May 1972 and thereafter at intervals not exceeding 75 hours time in service.