AD/DH 104/6 Engine Mount Attachment Brackets - Inspection 3/75 Amdt 1

Applicability: All models not modified in accordance with TNS CT (104) Nos. 50 and 65.

Document: Hawker Siddeley TNS CT(104) Nos. 50 Issue 3 and 65 Issue 4.

Compliance: At intervals not exceeding 50 hours time in service after 30 April 1973.