AD/DO-27/1 Steel Band Tensioners - Replacement 8/61

Applicability: All models Q-1, Q-3, Q-4 and H2.

Requirement:

1. Replace the steel band tensioners (Drawing No. 27-404-01 H02) with tension chains (Drawing No. 27-416-01 H02).

2. SB No. 27/11 dated 22 February 1961, issued by Dornier-Merke G.m.b.H Munchen-Neuaubing, Federal Republic of Germany, covers the modification work required. or

3. LBA AD 6.27.

Compliance: Before 1 September 1971.