AD/DO-27/8 Wing Fuselage Attachment - Inspection NK

Applicability: All D0-27Q and H series not modified in accordance with Dornier TB no. 27-33.

Document: Dornier TB No. 27-33.

Compliance: Within 100 hours time in service after 15 April 1969 and thereafter at intervals not exceeding 100 hours time in service.