AIRWORTHINESS DIRECTIVE

On the commencement date specified below, and for the reasons set out in the background section, this airworthiness directive (**AD**) is repealed by CASA ADCX 008/21.

Airbus Helicopters (Eurocopter) EC 120 Series Helicopters

AD/EC 120/14 Amdt 1 — Tail Rotor Driveshaft - Rear Driveshaft Friction Ring — 20/2021

Requirement: CANCELLED.

This AD is cancelled on 1 October 2021.

Background: The requirements of this AD have been superseded by EASA AD cancellation 2007-0211-CN issued on 23 September 2021 with an effective date of 23 September 2021.