Eurocopter AS 350 (Ecureuil) Series Helicopters

AD/ECUREUIL/32 Fuel Filter 11/2001 Amdt 1

Requirement: CANCELLED.

Background: This Directive was originally issued to require confirmation of certain fuel filters by manufacturer and part number were effectively tightened and leak checked each time the filter was disturbed. The terminating action being the replacement of filter assemblies of concern with a filter assembly incorporating a differential pressure switch. The maintenance action required following fuel filter maintenance is adequately detailed in the maintenance manual. All applicable helicopters now incorporate a fuel filter assembly with an electronic fuel filter bypass warning pressure switch.