AD/ECUREUIL/45 Tail Rotor Pitch Control Lever Expansion Pin 9/91 DM

Applicability: All AS350 Helicopters versions B, B1, B2 and D.

Requirement: Action in accordance with the Technical Requirements of DGAC TAD T91-137-059 (B).

Note: Aerospatiale TSB 01-33 refers.

Compliance: A specified in the requirement document with revised effective date of 10 July 1991.

Background: One lug of the tail rotor gearbox control lever hinge yoke failed through incorrect assembly of the bushes on the expansion pin.