AD/ECUREUIL/12 Tail Rotor Blade Pitch Horn 5/87 Amdt 3

Applicability: All models.

Requirement: Action in accordance with Aerospatiale AS 350 Telex Service 01.07B.

Compliance: As detailed in the requirement document.

Note: This inspection may be accomplished by the pilot-in-command, in which case the precise AD reference shall be entered in a certification made on the Maintenance Release coincident with that for the daily inspection.

Background: The manufacturer has introduced a retirement life for the subject tail rotor pitch horns. Amendment 3 changes the Compliance statement regarding certification of the inspection.