AD/ECUREUIL/43 Amdt 1 — Rotating Swashplate Bearing — 3/99

CANCELLED.

Background

The requirements of this Directive have now been incorporated into the Eurocopter AS 350 Master Servicing Recommendation Manual in the Airworthiness Limitations Section, 05.99.00, and therefore deemed to be mandatory for all operators. This Directive is therefore cancelled with effect 25 March 1999.