AD/ECUREUIL/33 Starflex Arms and MGB Suspension Bars 10/86

CANCELLED - Superseded by AD/ECUREUIL/34.

Background: The manufacturer after further investigation, believes the problem is associated with a vibration frequency, coupled with lack of stiffness of certain components. A more extensive inspection procedure has been called for which varies from the original Directive.