AD/ECUREUIL/17 Tail Rotor Drive Shaft Bearing - Inspection 5/87

CANCELLED.

Background: Superseded by AD/ECUREUIL/36.