COMMONWEALTH OF AUSTRALIA

CIVIL AVIATION SAFETY AUTHORITY

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this airworthiness directive (***AD***) is revoked by CASA ADCX 015/15.

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

AD/ECUREUIL/57 Amdt 1 — Tail Rotor Drive Shaft Bearings — 21/2015

Requirement: CANCELLED.

This AD is cancelled on 19 October 2015.

Background: The requirements of this AD have been superseded by EASA AD 2015-0195 issued on 23 September 2015.