AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/ECUREUIL/5.

Eurocopter AS 350 (Ecureuil) Series Helicopters

AD/ECUREUIL/5 Tail Rotor Control Fixed Plate - Inspection of Self Aligning Bearing 8/2009

Requirement: CANCELLED.

This AD is cancelled on 30 July 2009.

Background: This unique Australian AD specified an inspection in accordance with Aerospatiale SB No. 05.01 at 50 hour intervals. The periodic inspections could be terminated when the helicopter was modified. The AD was published in 1979 and is no longer required.

David Villiers
Delegate of the Civil Aviation Safety Authority

18 June 2009