AD/ELECT/35 Amdt 1 — Bendix Magneto - Housing Distortion - Inspection and Modification — 2/98

CANCELLED.

Background: This AD previously mandated use of the manufacturers' Service Bulletins which have now been incorporated into the magneto manufacturer's Service Manual.