AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/ELECT/16.

Electrical Equipment

AD/ELECT/16 — Magneto - Bendix Scintilla Distributor Gear - Inspection — 2/2009

Requirement: CANCELLED.

This AD is cancelled on 12 February 2009.

Background: This unique Australian AD raised in 1966 against Bendix Scintilla Service Bulletin (SB) No. 510 required all S600 series Bendix Scintilla magnetos fitted with distributor gears P/N 10-357060 or 10-357060A to be inspected until modified by incorporation of gears P/N 10-357060B.

Compliance was at intervals not exceeding 100 hours TIS until incorporation of gears P/N 10-357060B.

As all affected aircraft would have been inspected and modified by now, this AD is considered to be no longer required.

James Coyne
Delegate of the Civil Aviation Safety Authority

23 December 2008