AD/ELECT/30 Bendix Magneto Coil Retainer Plug Inspection 2/98 Amdt 2

CANCELLED.

Background: This AD previously mandated use of the manufacturers' Service Bulletins which have now been incorporated into the magneto manufacturer's Service Manual.