AD/ELECT/25 Amdt 1 — Slick Magneto Hub - Impulse Coupling Replacement — 2/98

CANCELLED.

Background: This AD previously mandated use of the manufacturers' Service Bulletins which have now been incorporated into the magneto manufacturer's Service Manual.