Pratt and Whitney Piston Engines

AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PW-P/6.

AD/PW-P/6 Master Rod Bolt - Inspection 12/2000

Requirement: CANCELLED.

Background: The P&W R1830 engine overhaul manual has been revised to require replacement of P/No 23262 master rod bolts with bolts, P/No 74569. The requirements of this Directive have, therefore, been adequately addressed.

Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

20 October 2000

The above AD is notified in the *Commonwealth of Australia Gazette* on 1 November 2000.