Pratt and Whitney Piston Engines

AD/PW-P/1 Link Pin Plug Staking - Modification 10/82

CANCELLED.

Background: This Directive is cancelled because the maintenance manual (P//N 118610, revised September 1977) does, on page 7-10 permit the continual operation of the engine after a verified loss of one or more of the subject link pin plugs.