
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AIRCON/3.

Airconditioning Equipment

AD/AIRCON/3

**Godfrey Cabin Supercharger
Type 15 - Rotor Balance - Inspection**

10/2009

Requirement: CANCELLED.

This AD is cancelled on 24 September 2009.

Background: This unique Australian AD raised in 1968 required an inspection to dynamically balance cabin supercharger rotors in accordance with technique specified in the approved overhaul manual.

Compliance was: New Rotors: Before initial installation in an aircraft. Used Rotors: Before installation in an aircraft following each overhaul completed after 30 January 1968.

The requirements of this AD have been superseded by legislation requiring compliance with approved maintenance data; therefore this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

14 August 2009