

Airbus Industrie A319, A320 and A321 Series Aeroplanes

---

**AD/A320/81**

**Connecting Angle Between Frame 56  
and Frame Support at Stringer 38**

**5/97**

Applicability: A320, all models and serial numbers without Airbus Industrie Mod 20941 embodied, or Airbus Industrie SB A320-53-1011 incorporated.

Requirement: Inspect in accordance with A320-53-1084 Rev 1.

*Note: DGAC AD 96-237-090(B) refers.*

Compliance Before the accumulation of 20 000 flights; thereafter at intervals not exceeding 12 000 flights; unless cracking has been detected, in which case, in accordance with thresholds and intervals specified in the Requirement Document.

This Airworthiness Directive becomes effective on 24 April 1997.

Background: This Directive is raised in order to detect cracking in the subject connecting angle, which could affect the structural integrity of the aircraft.