

AMD Falcon 50 and 900 Series Aeroplanes

---

**AD/AMD 50/12      Right Hand Electrical Cabinet Wiring Harness      8/96**

**Applicability:** This Directive is applicable to Mystere-Falcon 50 aeroplanes with equipment racks fitted between frames 9 and 11, aft of the right hand electrical cabinet.

**Requirement:** Action in accordance with Dassault Aviation Falcon 50 Mandatory Service Bulletin F50-256 dated 24 April 1996.

*Note: DGAC AD 96-094-017(B) dated 24 April 1996 refers.*

**Compliance:** Within 300 hours time in service after 18 July 1996 or prior to 31 December 1996, whichever occurs first.

**Background:** This Directive is issued following a report from Dassault Aviation advising of an incident resulting from a chafed wiring harness aft of the right hand electrical cabinet. The actions specified by this Directive are designed to decrease the likelihood of wire harness chafing occurring in this area.