

COMMONWEALTH OF AUSTRALIA
CIVIL AVIATION SAFETY AUTHORITY
SCHEDULE OF AIRWORTHINESS DIRECTIVES

(Civil Aviation Regulations 1998), PART 39 - 105

Background: Following an incident involving a similar type of aeroplane, the DGAC identified the lack of rapid cabin depressurisation emergency procedures in the AFMs.

This Directive provides interim AFM emergency procedures for rapid cabin depressurisation which may be removed when AFM changes are incorporated.



Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

16 January 2001