

Boeing 727 Series Aeroplanes

AD/B727/11

**Wing Rib Doubler Replacement
at Wing Buttock Line 3480**

11/65

Applicability: All models.

Document: Boeing SB No. 57-45.

Compliance: Before 20000 hours total time in service.