

Boeing 727 Series Aeroplanes

AD/B727/71

**Outboard Aileron Tab Mast
Fitting - Inspection and Modification**

11/75

Applicability: All models with S/Nos. as detailed in SB No. 57-137.

Document: 1. Boeing SB No. 727-57-137, Rev. 2; or
2. FAA AD 75-20-09, Amdt. 39-2375.

Compliance: 1. Inspect: Initially within 500 hours time in service after 28 November 1975 unless already accomplished, and thereafter at intervals not exceeding 1500 hours time in service until modified by replacement of all blind rivets with bolts and nut-plates in accordance with document 1.
2. Modify: Before 1 July 1977.