

Boeing 727 Series Aeroplanes

AD/B727/86 **Passenger Oxygen Mask Tube Attachment** **4/80**

Applicability: All models with “Carry-all” interior passenger service units.

Document: 1. Boeing SB No. 727-35-A18; or
2. FAA AD 79-23-02.

Compliance: Within 2000 hours time in service after 30 April 1980.

Background: Advice from overseas indicates that modification of the passenger oxygen manifold orifice fittings is necessary to prevent passenger oxygen supply tubes from inadvertently disconnecting.