

Boeing 737 Series Aeroplanes

AD/B737/38

Fuselage Lap Joints BS259 to BS1016

5/90

Applicability: Line number 001 to 291 inclusive.

Requirement: Action in accordance with the technical requirements of FAA AD 89-09-03, paras A to D.

Note: Incorporation of the repairs/modifications in this Directive partially terminate the requirements of AD/B373/37.

Compliance: In accordance with the Requirement Document.

Background: This Directive requires terminating action for parts of AD/B737/37. This is in recognition that inspection procedures alone may not ensure an adequate level of structural integrity at the skin splices.