

Boeing 737 Series Aeroplanes

AD/B737/44

Fuel Tank Access Doors

9/90

Applicability: Models 737-100 and -200 with line positions 1 through 1456.

Models 737-300 with line positions 1001 through 1505, and 1508.

Requirement: For 737-100 and -200: Action in accordance with Boeing SB 28A1078 Rev 1.

For 737-300: Action in accordance with Boeing SB 28-1081 Rev 1.

Compliance: Prior to 30 October 1991.

Background: The incorporation of the Service Bulletins enables aircraft to comply with FAR 25.963(e) which provides for some fuel tank access panels to have a higher resistance to impact to reduce possibility of penetration from engine debris or objects thrown by the aircraft tyres.