

Boeing 737 Series Aeroplanes

---

**AD/B737/70                      Thrust Reverser - Auxiliary Slider Track Liner                      11/92**

Applicability:    All Model 737-300, -400 and -500 series.

Requirement:    Action in accordance with the technical requirements of FAA AD 91-25-06.

*Note: Boeing Service Bulletin 737-78-1048 Revision 1 refers.*

Compliance:    As detailed in the Requirement Document with an effective date of 15 October 1992.

Background:     Inspection, repair and replacement as necessary of each thrust reverser auxiliary track, track liner and slider fitting has been prompted by two in-flight incidents in which a thrust reverser translating sleeve panel has separated from the aircraft.