

Boeing 737 Series Aeroplanes

---

**AD/B737/74**

**Thrust Reverser Actuator Piston Seal**

**2/93  
DM**

Applicability: Boeing 737-300,-400 and -500 series aeroplanes as listed in Boeing Service Bulletin 737-78A1055, dated 2 April 1992.

*Note: FAA AD 92-24-04 refers.*

Requirement: Action in accordance with Boeing Service Bulletin 737-78A1055 dated 2 April 1992.

Compliance: By 1 January 1994.

Background: Analysis by the manufacturer indicates that a potential exists for leakage across the piston seal in the thrust reverser actuator. The actions specified in this AD are intended to prevent uncommanded deployment.