

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B737/112.

---

### Boeing 737 Series Aeroplanes

### AD/B737/112      Yaw Damper Coupler Internal Rate Gyroscope      3/2005

Requirement:      CANCELLED.

This AD is cancelled on 17 March 2005.

Background:      The repetitive inspection requirements of this Directive have been terminated by the replacement of the single electro-mechanical rate gyro by a dual solid-state yaw rate sensor as required by AD/B737/123.



James Coyne  
Delegate of the Civil Aviation Safety Authority

4 February 2005