

Boeing 747 Series Aeroplanes

AD/B747/20 Inboard Pylon Diagonal Brace Forward Fuse Pins 3/93
Amdt 1

CANCELLED.

Background: The issue of FAA AD 93-01-05 combined the new requirements for AD/B747/20A and AD/B747/39. The new requirements for AD/B747/20A have been incorporated into AD/B747/39 Amdt 1.