

Boeing 747 Series Aeroplanes

AD/B747/31 **Aileron Control System - Modification** **6/83**

Applicability: All model 747 with S/Nos. referenced in Boeing SB. 27-2065, SB 27-2095, SB 27-2161 and SB 51-2032 as applicable.

Document: Boeing SBs 747-27-2065, 747-27-2095, 747-27-2161, 747-51-2032.

Note: FAA AD 82-02-10 refers.

Compliance: Unless previously accomplished, within 3000 hours time in service after 30 June 1983.

Background: Numerous occurrences of binding in the aileron control system are attributed to the accumulation of ice on the aileron control system in the wing gear wheel well area.