

Boeing 747 Series Aeroplanes

**AD/B747/33
Amdt 2**

Wing Trailing Edge Flap Tracks

8/90

Applicability: Model B747 line numbers 1 through 584 except B747SP.

Requirement: Action in accordance with Boeing SB747-57A2225 Rev. 4.

Note: FAA AD 83-21-02 refers.

Compliance: As detailed in the Requirement Document.

Background: Water accumulation in the track aft cavity has resulted in corrosion and consequent aft web cracking. Amendment 1 references the latest revision of the Requirement document, which adds terminating action. Amendment 2 clarifies aircraft affected.