

Boeing 747 Series Aeroplanes

AD/B747/66 **Lower Lobe Cargo Door Locking System** **3/91**
Amdt 2

Applicability: Model 747 series line number 001 and subsequent.

Requirement: Unless already accomplished; action in accordance with the technical requirements of FAA AD 90-09-06 Amdt 39-6581.

Note: Boeing SB's 747-52A2206 and 747-52A2209 refer.

Compliance: As specified in the Requirement Document.

Background: A lower lobe forward cargo door partially opened in flight due to damaged lock sectors. Amendment 1 was raised in response to the FAA decision, following a second occurrence, to accelerate the compliance time previously required by AD 88-12-04, and for installation of certain modifications as well as additional inspections and tests in the interim.

This amendment is raised to reflect an additional requirement of FAA Amdt 39-6581, AD 90-09-02; which supersedes Amdt 39-6166, AD 89-05-54.