

Boeing 747 Series Aeroplanes

---

**AD/B747/127**

**Engine Mount Bolt Inspection**

**9/94**

Applicability: Boeing 747 aircraft fitted with Pratt & Whitney JT9D-3 and -7 series engines.

Requirement: Action in accordance with the requirements of FAA AD 94-10-05.

Compliance: Effective 18 August 1994, as specified in the FAA AD.

Background: There have been reports of the forward lower engine mount bolts migrating out of the mount due to loss of the retaining nuts.