
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B747/194.

Boeing 747 Series Aeroplanes

AD/B747/194

Horizontal Stabilizer Fuel Tank Pumps

5/2002

Requirement: CANCELLED.

Background: AD/B747/270 supersedes the requirements of this Airworthiness Directive by cancelling the need for repetitive inspections of the horizontal stabilizer fuel tank pumps. The FAA has new information (FAA AD 2001-12-21) from the fuel pump manufacturer that provides initially for verification of pumps installed in the centre wing fuel tank and the horizontal stabiliser fuel tank, and as necessary, replacement by new improved pumps.



Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

7 April 2002