

Boeing 747 Series Aeroplanes

AD/B747/204

Number 1 Main Entry Door Cutout

7/99

Applicability: Model 747 series aircraft, line numbers 1 through 685.

Requirement: Perform eddy current inspection in accordance with the technical requirements of FAA AD 99-07-03 Amdt 39-11085.

Note: Accomplishment of the repair or preventative modifications specified in ASB 747-53A2414, constitutes terminating action for the repetitive inspection requirements of this Directive for that repaired/modified edge frame web and doubler.

Compliance: Initial and repetitive inspection as specified in the Requirement Document with a revised effective date of 15 July 1999.

This Airworthiness Directive becomes effective on 15 July 1999.

Background: The FAA received reports of fatigue cracks found in the edge frame web and doubler at the door stop number 1 of the number 1 main entry door cutout.