

Boeing 767 Series Aeroplanes

**AD/B767/7 Passenger/Crew Door Latch Overcentre Mechanism 4/86
DM**

Applicability: All model 767 with line position 2 to 121 and 124 to 127.

Requirement: Action in accordance with Boeing SB 767-52-0041.

Note: FAA AD 86-02-01 refers.

Compliance: Prior to 31 March 1986.

Background: Boeing Co have reported that a significant percentage of self locking nuts P/N BACN10JC6CM in stock do not meet specified locking torque requirements.