

Boeing 767 Series Aeroplanes

AD/B767/30

Cabin Partitions

13/89

Applicability: Model 767 aeroplanes as listed in Boeing Alert SB 767-25A0135 dated 6 July 1989.

Requirement: Action in accordance with Boeing Alert SB 767-25A0135.

Note: FAA AD 89-19-03 refers.

Compliance: Prior to 31 January 1990 unless previously accomplished.

Background: Country of origin AD. Defective attachment bolts allowed collapse of cabin partition on which an attendant seat is mounted.