

Boeing 767 Series Aeroplanes

AD/B767/68

Galley Tie Rods

8/92

Applicability: Model 767 series, as listed in Boeing SB 767-25-0160.

Requirement: Replace the aft galley tie rods IAW Boeing SB 767-25-0160 or SB 767-25-0160 Revision 1.

Note: FAA AD 92-08-05 Amdt 39-8216 refers.

Compliance: Prior to 23 September 1992.

Background: The FAA requires tie rod replacement following a determination that certain aft galley installations do not meet the requirements for emergency landing conditions. The effective date required by the FAA is extended by one month.