

Casa 212 Series Aeroplanes

AD/CASA/19

False Spar, Flap Housing Area

9/96

Applicability: All models.

Requirement: 1. Action in accordance with CASA document COM 212-224 dated 28 November 1990.
2. Repair any cracking in accordance with a scheme approved pursuant to CAR 35.

Note: Spanish DGAC AD 02/96 refers.

Compliance: Within 1200 hours time in service after 15 August 1996. Where no cracking is found repeat inspection at intervals not exceeding 1200 hours time in service.

Background: Cracking has been detected in the area defined in the Requirement Document.