

Agusta A109 Series Helicopters

AD/A109/9

Engine Mount Installation

6/87

- Applicability: All models A109A and A109AII up to and including S/N 7361 except S/N 7359.
- Requirement: Action in accordance with Bollettino Tecnico 109-61 Part I and Part II.
- Compliance: Within 100 hours time in service after 4 June 1987 or at the next scheduled inspection for Maintenance Release issue after 4 June 1987, whichever is later.
- Note: RAI AD 87-43/109-42 refers.*
- Background: Chafing of an oil scavenge line against a mount leg has initiated corrosion which has in one case penetrated through the tubing.